

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM-69186	
2. NAME OF OPERATOR JNC Resources		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 6506 S. Lewis Suite 162 Tulsa, OK 74136		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990' FNL & 990' FEL Section 9, T16N., R2W.		8. FARM OR LEASE NAME Anthony	
14. PERMIT NO.		9. WELL NO. #2	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6245' GL		10. FIELD AND POOL, OR WILDCAT Wildcat	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 9, T16N-R2W.	
		12. COUNTY OR PARISH Sandoval	13. STATE NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Request permission to P/A this well as per instructions from the Farmington, NM BLM office exactly as before when this well was known as the Shirl #1.

Fill hole w/mud. Run cement from 2700' to 2550'. Filled holes w/9.2# mud.
Run cmt. from 1895' to 1793'/ Use 9.2 mud to displace all Plugs.
Pump cmt. from 1520' to 1420'.
Set cmt. plug from 1053' to 953'.
Set plug at 100' to surface.
Install Dry hole marker. Set dry hole marker.

GEOLOGICAL MARKERS

Entrada	2640' - 2828'	Morrison	1848' - 2544'	Gallup	940' - 983
Todolito	2544' - 2640'	Dakota	1470' - 1848'	Mancos	
				Shale	0 - 940'

RECEIVED

DEC 30 1987

APPROVED

18. I hereby certify that the foregoing is true and correct

SIGNED *Neil S. Dollar*

TITLE Agent

OIL CON. DIV.

DATE 12-18-87

(This space for Federal or State office use)

DIST. 3

DEC 23 1987

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

James E. Edwards Jr.
AREA MANAGER
FARMINGTON RESOURCE AREA

*See Instructions on Reverse Side