

37. SUMMARY OF POROUS ZONES. (Show all important zones of porosity and contents thereof, cored intervals, and drilling, etc., including depth interval tested, casing used, pump tool open, flowing and shut-in pressures, etc.)

LOGIC MARKERS

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	LOGIC MARKERS	
				NAME	TOP
				MEAS. DEPTH	ENT. DEPTH
Ojo Alamo	370'				
Fruitland	553'				
Picture Cliff	753'				
Lewis	898'				
Chacra	1160'				
Cliff House	1575'				
Menefee	2255'				
Point Lookout	2990'				
Mancos	3152'				
Casing Pt(7")	3706'				
Callup "A"	3873'				
Callup "B"	4015'				
Callup "C"	4109'				
Callup "D"	4230'				
Total Depth	4376'				