Form 3160-5 (November 1983) (Formerly 9-331)	UNITED STATES DEPARTMENT OF THE IN BUREAU OF LAND MANAGE		Form approved. Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO. NM-29168
SUNI (Do not use this	DRY NOTICES AND REPORT FOR PERMIT—" for PROPORTION FOR PERMIT—" for	RTS ON WELLS r plug back to wike ent reproductively reach proposals.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME N/A
OIL GAB		.11N 1 1	7. UNIT AGREEMENT NAME
WELL KM WELL 2. NAME OF OPERATOR	OTHER	9011 1 1986	N/A 8. FARM OR LEASE NAME
	Oil Droduger Inc	BUREAU OF LAND	<pre>/ Tayler 29</pre>
Gary-Williams Oil Producer, Inc. BUREAU OF LAND MANAGEMENT 3. ADDRESS OF OPERATOR			FMZ 9. WHILL NO.
Gary-Williams Oil Producer, Inc. 3. ADDRESS OF OPERATOR 115 Inverness Drive East, Englewood, CO 80112-5116			EA 9
4. LOCATION OF WELL (Re See also space 17 belo At surface	10. FIELD AND POOL, OR WILDCAT		
677' FEL & 200	Rio Puerco Mancos 11. SPC., T., B., M., OR BLE. AND SURVEY OR AREA		
			NE SE 29-T21N-R3W
14. PERMIT NO.	15. ELEVATIONS (Show wh	ether DF, RT, GR, etc.)	12. COUPTY OR PARISH 13. STATE
	6954 GR		Sandoval NM
Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:			BARQUENT REPORT OF:
		7	REPAIRING WELL
TEST WATER SEUT-OF FRACTURE TREAT	PULL OR ALTER CASING	WATER SHUT-OFF PRACTURE TREATMENT	ALTERING CARING
SHOOT OR ACIDIZE	ABANDON®	SECOTING OR ACIDISING	
REPAIR WELL	CHANGE PLANS	(Other)	
	to temporarily SI well X	Nort Beneft to	suits of multiple completion on Well completion Report and Log form.)
17. Last rich inoposed or completed operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent dates.			
Gary-Williams Oil Producer, Inc. respectfully requests approval to temporarily shut in the Tayler 29, #9 well for an indefinate time period. Current depressed oil prices make this marginal well uneconomical to produce.			
This request is being done under the policy of suspension of production requirements for stripper oil wells on Federal and Indian lands.			
The Tayler 29, #9 produces from the Gallup formation. Production averaged about 1 BOPD.			
undevelop for tempo	e fact that there are remain ed hydrocarbond potential, a rary shut in status for this w t recoverable hydrocarbon re	a temporary shut in period well would prevent premat	is requested. Approval
		25 1986	6-24-57
OR CON DIV			
18. I hereby certify that the foregoing is true and correct DIST. 3			
SIGNED W. P.	Marx TITL	Operations Manager	DATE 6/9/86 APPROVED
(This space for Federa	al or State office use)		

APPROVED BY CONDITIONS OF APPROVAL, IF ANY: SEE ATTACHED FOR CONDITIONS OF APPROVAL

*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

TITLE .