195/8 @ 3624	5 214 W/18 1-3935	/E Cu.ft. 7 @-		Prod. Stim.	F		· "-	.	KK 35	57	↑ Gas R A
13	80/D ACE/D After <u>24</u>	Hrs. SICP	PSI After	Grav Days GOR		1st De 1st De	i. <u>Gas</u> i. <u>Oil <i>&</i></u>	,-14 <u>-8</u> 5	5		N 5 ,
10	PS	NITD X	Well Log		TEST DAT	A					
Ojo Alamo		C-103 /1///	✓ Plat X	1	Schd.	PC	Q	PW	PD	D	Ref.No.
Kirtland		C-104 2-17-86	Electric Log	/////						ļ	3063/7
Fruitland		1/2	C-122					ļ	<u> </u>		1
Pictured Cliffs		Ditr	Dfa						<u> </u>		30051
Chacra		Datr	Doc						<u> </u>	L	
Cliff House		water a 40						<u> </u>			
Menefee		* pumped capter	rent dr. ancel	(ca) 134ef.				ļ 			
Point Lookout	<u> </u>	1	a de la companya de l							ļ	
Mancos		1						<u> </u>			
Gallup	3490	1							<u> </u>	<u>.</u>	
Greenhorn		· · · · · ·								<u> </u>	
Dakota		1		40					<u> </u>		
Entrada				N/398				<u> </u>			
	<u> </u>	7	Ac	cres -40							

Ec 3160	
(November	1983)
(Formerly	9 - 331)


UNITED STATES

SUBMIT IN TRIPLICATES (Other instructions on re-

Form approved. Budget Bureau No. 1004-0135 Expires August 31, 1985

	TMENT OF THE INTERIOR EAU OF LAND MANAGEMENT		NM-25604	IND BERIAL NO.		
SUNDRY NO (Do not use this form for prouse "APPI	6. IF INDIAN, ALLOTTEE OR TRIBE NAME					
OIL X GAS OTHE			7. UNIT AGREEMENT NA	KE.		
2. NAME OF OPERATOR			8. FARM OR LEASE NAM	E		
Gary-Williams Oil Pr	llar, Agent	San Isidro 26				
3. ADDRESS OF OPERATOR			9. WELL NO.			
P. O. Box 399 Aztec,	NM 87410		#7			
4. LOCATION OF WELL (Report location See also space 17 below.) At surface	Rio Puerco Mancos					
1900' FNL &	11. BEC., T., B., M., OR BLK. AND BURYEY OR AREA					
RECEIVE						
RECEIVE	•		SWNE 26-T201	N-R3W		
14. PERMIT NO.	15. ELEVATIONS (Show whether DF,	RT, GR, etc.)	12. COUNTY OR PARISH	13. STATE		
DEC 02 1985	6984' G	R	Sandova1	NM		
16 BUBEAU OC LAND ALLA Chock	Appropriate Box To Indicate N	lature of Notice, Report, or (Other Data			
FARMINGTON RESOURCE AREA		SUBSEQ	QUENT REPORT OF:			
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING W	TELL		
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CA	SING		
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMEN	T*		
	CHANGE PLANS	(Other)				
(Other)	stimulate Menefee X 🛨	(Note: Report result Completion or Recom	s of multiple completion operation Report and Log for	m.)		
mont to this mork) *	OPERATIONS (Clearly state all pertinen ectionally drilled, give subsurface local PAA Gallup	t details, and give pertinent dater tions and measured and true verti	s, including estimated date cal depths for all markers	e of starting any and zones perti-		
Poquest no	umiccion to etimulate t	ha Manafaa 7ana Sa	t Cast Iron Bri	dao Plua		

Request permission to stimulate the Menefee Zone. Set Cast Iron Bridge Plug @ 3600' KB. Dump 50 sx cmt. on top. Gallup perfs are @ 3624' - 3935'. Perforate Menefee: 2176' - 2186', 2194' 2202', 2272' - 2282', 1 shot per '. Acidize each interval with 7½% HcL & if further stimulation is required, will frac with 23000# jelled KcL containing 29000# of 10-20 sand.



DIST. 3

18. I hereby certify that the foregoing is true and correct			APPROVED
SIGNED Hed Hollar	TITLE	Agent	Dec. 2, 1985
(This space for Federal or State office use)			Dec 6 Jel 19
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE		DATE M. MILLENBACH
COMBITIONS OF ALLMONIA, 22 AND			AREA MANAGER

*See Instructions on Reverse Side

NMOCD