Form 3160-5 (November 1983) (Formerly 9-331)	UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT	SUBMIT IN TRIPLICATE® (Other instructions on reverse side)	5. LEASE NOO-C
SUN (Do not use this	DRY NOTICES AND REPORTS ON form for proposals to drill or to deepen or plug back to Use "APPLICATION FOR PERMIT—" for such proposals.	WELLS to a different reservoir.	Nava

14. PERMIT NO.

16.

2. NAME OF OPERATOR

3. ADDRESS OF OPERATOR

Budget Bureau No. Expires August 31,	1004-0 1985	)13
5. LEASE DESIGNATION AND	SERIAL	NO.

Form approved.

m 3160-5 vember 1983) merly 9-331)  BUREAU OF LAND MAN	INTERIOR verse alde)	5. LEASE DESIGNATION AND ESELAL NO.  NOO-C-5755  6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND RE (Do not use this form for proposals to drill or to dec Use "APPLICATION FOR PERMIT	Navajo Allottee	
OIL GAS STREET	/	S. FARM OR LEASE NAME
NAME OF OPERATOR Robert L. Bayless	Natani	
P.O. Box 168, Farmington, NM 874	199 DECEMED	9. WBLL NO.  32  10. FIELD AND POOL, OR WILDCIT
LOCATION OF WELL (Report location clearly and in accords See also space 17 below.)  At surface		Rusty Chacra 11. sec., T., E., M., OR BLE. AND
1680' FNL & 2108' FEL	MAR 0 5 1986	Sec. 2. T21N, R6W
PERMIT NO. 15. BLEVATIONS (SI	BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA GL	12. COUNTY OF PARISH 13. STATE Sandoval NM
Check Appropriate Box To	Indicate Nature of Notice, Report, or C	Other Data
TEST WATER SHUT-OFF PULL OR ALTER CASIN MULTIPLE COMPLETE SHOOT OF ACIDIZE ABANDON*  REPAIR WELL CHANGE PLANS	FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other)	REPAIRING WELL  ALTERING CASING  ABANDONMENT®
(Note: Report results of multiple completion on V		

(Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.) \*

In response to your letter dated 2-6-86 and subsequent conversation between Mat Millenbach and Robert Bayless, the following actions have been taken:

- The reserve pit was to be fenced or a water analysis completed, an analysis has not been done because there is no longer any free water in the pit.
- Sandy spot in road has been graded as requested.



SIGNED LLW COTT	TITLE Petroleum Engineer	
(This space for Federal or State office use)		
APPROVED BY	TITLE	DATE
		i de la compania del compania de la compania de la compania del compania de la compania del compania de la compania de la compania de la compania del compania de la compania de la compania de la compania de la compania del compania

\*See Instructions on Reverse Side

PRINCE NO.

/