



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

GARREY CARRUTHERS
GOVERNOR

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

May 3, 1988

Kirby Exploration Co. of Texas
P.O. Box 1745
Houston, TX 77251

Re: Boiling Federal 22 #9 E-22-19N-3W


Gentlemen:

Our office has contacted you several times about the well completion report for the referenced well being incomplete. We have yet to receive the information we requested.

If there is a serious problem, please let us know and give us time by which you will comply.

Further delay will subject you to fines.

Sincerely,


Frank T. Chavez
District Supervisor

FTC/dj
Attachment

xc: Operator File
Well File



GARREY CARRUTHERS
GOVERNOR

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

1-8-87
12-11-87
Jim B. called him
12-8-87 will call
Back GenWood
info 12-8-87
1000 RIO BIAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

James Kovar

713-629-9370

Kirby Exploration Co. of Texas
OPERATOR

Poling Fed. 22 #9
WELL & LEASE NUMBER

22-19N-3W
LOCATION

Please submit information as indicated below for the above well.

- _____ C-102, Well Dedication Plat
- _____ C-103 (or Federal Form 9-331) - Notice of Intention To:

TEMP WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETS	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>

- _____ C-103 (or Federal Form 9-331) - Subsequent Report Of:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>

(Other) _____

- X C-105 (or Federal Form 9-330) - Well Record #37
- _____ Deviation Tabulation (notarized)
- _____ Administrative Order - MC DHC NSL NSP
- _____ Wire Line Logs (1 copy each)
- _____ Packer-Leakage Test Report
- _____ Other

On the back of the
completion report we
need the formation tops
need cubic feet
for the surface Inter. pressure

Remarks: We are unable to process the
C-105 until we receive the formation
tops.

Karen Ann Baird
District #3