

DA

J

30-043-20823

4-25-88

F. Loc. 2310/S; 1675/W Elev. 6771 GL Spd. Comp. TD PB
Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. T. @
Csg. Perf. Prod. Stim.

Grav. 1st Del. Gas
I.P. BO/D MCF/D After Hrs. SICP PSI After Days GOR 1st Del. Oil

TCPS		NiTD X	Well Log	TEST DATA							Ref.No.
Ojo Alamo		C-103	Plat X	Schd.	PC	Q	PW	PD	D		
Kirtland		C-104	Electric Log								
Fruitland			C-122								
Pictured Cliffs		Ditr	Dfa								
Chacra		Datr	Dac								
Cliff House											
Menefee											
Point Lookout											
Mancos											
Gallup											
Greenhorn											
Dakota											
Entrada											
		Acres 40									

P
O
O
OteroSanosteGLCo. SA S 6 T 22N R 4W U K Oper. Mallon Oil Co. Loe. Jic. 434 G No. 3

Jic. 434 G #3

K-6-22N-4W

MALLON OIL CC.

ABANDONED LOCATION

Jic. Cont. 434 (WC)
3162.3-1(I) (019)

AUG. 15 1989

CERTIFIED--RETURN RECEIPT REQUESTED
P-117-127-222

Mallon Oil Company
1099 18th Street, Suite 2750
Denver, CO 80202

Gentlemen:

Enclosed are your Applications for Permit to Drill (APDs) well No. (2) and (3) Jicarilla 434G, NW/4NE/4, NE/4SW/4, respectively, sec. 6, T. 22 N., R. 4 W., Sandoval County, New Mexico, Jicarilla Contract 434. As discussed with Kevin McCord of your company on August 9, 1989, the subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

Mark D. Holmes

FOR

Ron Fellows
Area Manager

Enclosures

cc: NMOCC, Aztec, NM
BIA, Dulce, NM

RECEIVED

AUG 17 1989

OIL CON. DIV.
DIST. 3