



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Farmington Resource Area
1235 Laplata Highway
Farmington, New Mexico 87401

TAKE
PRIDE IN
AMERICA

IN REPLY REFER TO:

NM-23050 (WC)
3162.3-1 (019)

RECEIVED

OCT 23 1991

OIL CON. DIV.
DIST. 3

OCT. 22 1991

Bannon Energy, Inc
c/o Daggett and Chenualt
Attention: Bob Larson
3539 East 30th, Suite 7B
Farmington, NM 87401

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

- ✓ 1. 6 Federal 6, sec. 6, T. 23 N., R. 7 W., Rio Arriba Co., NM,
Lease NM-23050.
- ✓ 2. 3 Lybrook Federal 24, sec. 24, T. 24 N., R. 7 W., Rio Arriba Co.,
NM, Lease NM-83502.
- ✓ 3. 4 Federal 31, sec. 31, T. 24 N., R. 7 W., Rio Arriba Co., NM,
Lease NM-33005.
- ✓ 4. 6 Federal 13, sec. 13, T. 23 N., R. 7 W., Rio Arriba Co., NM,
Lease SF-078360.
- ✓ 5. 17 Lybrook South, sec. 13, T. 23 N., R. 7 W., Rio Arriba Co., NM, -- Fed. 13 #8
Lease SF-078360.
- ✓ 6. 18 Lybrook South, sec. 14, T. 23 N., R. 7 W., Rio Arriba Co., NM,
Lease SF-078360.
- ✓ 7. 19 Lybrook South, sec. 14, T. 23 N., R. 7 W., Rio Arriba Co., NM,
Lease SF-078360.
- ✓ 8. 20 Lybrook South, sec. 14, T. 23 N., R. 7 W., Rio Arriba Co., NM,
Lease SF-078360.
- ✓ 9. 21 Lybrook South, sec. 14, T. 23 N., R. 7 W., Rio Arriba Co., NM,
Lease SF-078360.
- ✓ 10. 23 Lybrook South, sec. 18, T. 23 N., R. 6 W., Rio Arriba Co., NM,
Lease SF-078360.
- ✓ 11. 24 Lybrook South, sec. 19, T. 23 N., R. 6 W., Sandoval Co., NM,
Lease SF-078360.
- ✓ 12. 25 Lybrook South, sec. 19, T. 23 N., R. 6 W., Sandoval Co., NM,
Lease SF-078360.
- ✓ 13. 26 Lybrook South, sec. 19, T. 23 N., R. 6 W., Sandoval Co., NM,
Lease SF-078360.

ABANDONED LOCATION

14. 27 Lybrook South, sec. 19, T. 23 N., R. 6 W., Sandoval Co., NM,
Lease SF-078360.

15. 28 Lybrook South, sec. 19, T. 23 N., R. 6 W., Sandoval Co., NM,
Lease SF-078360.

16. 33 Lybrook South, sec. 14, T. 23 N., R. 7 W., Rio Arriba Co., NM,
Lease SF-078360.

As discussed with Bob Larson, a representative of your company on October 16, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

John L. Keller
Chief, Branch of Mineral Resources

16 Enclosures

cc:
New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410

Lybrook Gal. Co. RA S 6	T 23N R 7W	UD Oper. Bannon Energy, Inc.	Les. Federal 6	No. 6 ✓
DevFrk Gal. Co. RA S 24	T 24N R 07W	UB Oper. Bannon Energy, Inc.	Les. Lybrook Federal 24	No. 3 ✓
Lybrook GalCo. RA S 31	T 24N R 07W	UA Oper. Bannon Energy, Inc.	Les. Federal 31	No. 4 ✓
Lybrook GalCo. RA S 13	T 23N R 07W	UN Oper. Bannon Energy, Inc.	Les. Federal 13	No. 6 ✓
Lybrook GalCo. RA S 13	T 23N R 07W	UP Oper. Bannon Energy, Inc.	Les. Federal 13	No. 8 ✓
Lybrook GalCo. RA S 14	T 23N R 07W	UK Oper. Bannon Energy, Inc.	Les. Federal 14	No. 5 ✓
Lybrook GalCo. RA S 14	T 23N R 07W	UL Oper. Bannon Energy, Inc.	Les. Federal 14	No. 7 ✓
Lybrook GalCo. RA S 14	T 23N R 07W	UM Oper. Bannon Energy, Inc.	Les. Federal 14	No. 6 ✓
Lybrook GalCo. RA S 14	T 23N R 07W	UN Oper. Bannon Energy, Inc.	Les. Federal 14	No. 8 ✓
Lybrook GalCo. RA S 14	T 23N R 07W	UP Oper. Bannon Energy, Inc.	Les. Federal 14	No. 10 ✓
Lybrook Gal. Co. RA S 18	T 23N R 06W	UL Oper. Bannon Energy, Inc.	Les. Federal 18	No. 4
Lybrook GalCo. SA S 19	T 23N R 06W	UD Oper. Bannon Energy, Inc.	Les. Federal 19	No. 6 ✓
Lybrook GalCo. SA S 19	T 23N R 06W	UL Oper. Bannon Energy, Inc.	Les. Federal 19	No. 10 ✓
Lybrook GalCo. SA S 19	T 23N R 06W	UN Oper. Bannon Energy, Inc.	Les. Federal 19	No. 15 ✓
Lybrook GalCo. SA S 19	T 23N R 06W	UP Oper. Bannon Energy, Inc.	Les. Federal 19	No. 17 ✓
Lybrook GalCo. SA S 19	T 23N R 06W	UH Oper. Bannon Energy, Inc.	Les. Federal 19	No. 9 ✓

- N-18-23N-06W — Fed. 18 # 7 —

F

30-043-20846

09-14-90

F. Loc. 629/S; 704/E Elev. 7033 GL Spd. _____ Comp. _____ TD _____ PB _____
 Cu. ft. _____ Cu. ft. _____ Cu. ft. _____
 Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. T. _____ @ _____
 Csg. Perf. _____ Prod. Stim. _____

T
R
A
N
S

BO/D _____ Grav. _____ 1st Del. Gas
 MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ 1st Del. Oil

TOPS		NITD	Well Log	TEST DATA						
Ojo Alamo		C-103	Plat <u>X</u>	Schd.	PC	Q	PW	PD	D	Ref. No.
Kirtland		C-104	Electric Log							
Fruitland			C-122							
Pictured Cliffs		Ditr	Dfa							
Chacra		Datr	Dac							
Cliff House										
Menefee										
Point Lookout										
Mancos										
Gallup										
Greenhorn										
Dakota										
Entrada										
		Acres <u>40</u>								

P
o
o

Lybrook Gal Co. SA S 19 T 23N R 06W U P Oper. Bannon Energy, Inc. Lse. Federal 19

No. 17

Federal 19 #17

P-19-23N-06W

BANNON ENERGY, INC.