

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe**
Lease No. **27-079120**
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	Coring	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 19, 19 58


Kimbeto Unit
Well No. **1** is located **330** ft. from **N** line and **1900** ft. from **E** line of sec. **26**
NE/4 NE/4 **26** **22N** **10W** **100P**
(¼ Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat (Kimbeto) **San Juan** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the ~~surface~~ **ungr. grad** above sea level is **6357** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drill to 3536' and cut core #1 from 3485-3536'. Cut and rec 33'. Sd and shale. No show. Cut core #2 from 3536-3591'. Cut and rec 33'. Sd w/scattered shale. No show. Cut core #3 from 3591-3644'. Cut and rec 33'. Sd and shale. No show. Prep to drill ahead.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Northwest Production Corp.**

Address **520 Sioux Building**

Albuquerque, New Mexico

By **RAY PHILLIPS**
Ray Phillips

Title **Mgr. Prod Opr**