


Form 9-331a
(Feb. 1951)



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe**
Lease No. **25-079120**
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 19, 1958


Kimbeto Unit
Well No. **1** is located **330** ft. from **N** line and **1980** ft. from **W** line of sec. **26**
26 (1/4 Sec. and Sec. No.) **27N** **10W** **RMP**
Wildcat (Dehote) **San Juan** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the **6337** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD 4785'. Propose to spot 35 cu cmt plug fr 4785-4685; 35 cu plug fr 4550-4450; 35 cu plug fr 3300-3400; 65 cu plug fr 250-100; 5 cu plug fr 15'-surface. Install marker and abandon well.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Northwest Production Corp.**
Address **120 Simon Building**
Albuquerque, New Mexico
By **Ray Phillips**
Title **Mgr, Prod Opr**