

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ 1130' FNL - 1130' FEL

2. NAME OF OPERATOR  
McElvain Oil and Gas Properties, Inc.

3. ADDRESS OF OPERATOR  
P.O. Box 2148, Santa Fe, NM 87502-2148

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface  
1130' FNL - 1130' FEL

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
6858 DF

5. LEASE DESIGNATION AND SERIAL NO.  
NM-048989

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Warner Federal

9. WELL NO.  
1

10. FIELD AND POOL, OR WILDCAT  
Alamito-Gallup

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 10, T22N, R8W

12. COUNTY OR PARISH 13. STATE  
San Juan New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐  
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐  
SHOOT OR ACIDIZE ☐ ABANDON\* ☐  
REPAIR WELL ☐ CHANGE PLANS ☐

(Other) Plug back and recomplete

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐  
FRACTURE TREATMENT ☐ ALTERING CASING ☐  
SHOOTING OR ACIDIZING ☐ ABANDONMENT\* ☐  
(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

Move in rig. Pull rods and tubing.

Set cast iron bridge plug at 4600' and squeeze off perforations with cement.

Run cement bond log. Perform remedial cement work if required.

Perforate and test the Chacra formation.

RECEIVED  
FEB - 6 1995

OIL CON. DIV.  
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED Anna M. Schlegel TITLE Expl. & Prod. Administrator DATE January 16, 1995

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

APPROVED

JAN 20 1995

DISTRICT MANAGER