

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL ☐ WELL GAS ☐ WELL OTHER ☒ Wildcat

2. NAME OF OPERATOR

Bco, Inc.

3. ADDRESS OF OPERATOR

P.O. Box 669 Santa Fe, N.M. 87501

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

790' FNL 790' FWL Sec 17 T22N R9W NMPM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

GR 6424

NM-5988

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal E

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR B.L.K. AND SURVEY OR AREA

17-22N-9W NMPM

12. COUNTY OR PARISH 13. STATE

San Juan

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data:

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☒
☒
☐
☐

PULL OR ALTER CASING

☒
☐
☒
☐

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

WATER SHUT-OFF

☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Set cement retainer at 3100' and plug Gallup perforations (3655-3842) with 75 sacks of cement, thereby abandoning well permanently from T.D. thru 3100'.

Perforate w/2 shots at 2900' & try to get circulation to surface. If successful, cement with 350 sacks 50-50 POZ.

If unsuccessful, try to block squeeze between 2580-2900.

If unsuccessful, perforate 2850;2844;2823;2814;2810;2800;2706;2694;2655;2645;2626 and 2614 and squeeze perfs with cement.

If successful cement job obtained perforate and test the following:

Menefee 2619-2622 & 2648-2651

Point Lookout 2697-2700

Mancos Transition 2802-2806; 2818-2820; 2845-2847

18. I hereby certify that the foregoing is true and correct

SIGNED

Harry R. Bugh

TITLE

President

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

OIL CON. COM.

DIST. 3

DATE 9/7/77