

B.L.M. Farmington

Robert Ramirez

Form 9-331
(May 1983)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved
Budget Bureau No. 42-R14

5. LEASE DESIGNATION AND STATE NO.

NM-5454

6. IF INDIAN, AGENCY OR TRIBAL NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal F

9. WELL NO.

1

10. FIELD AND FORM OF WILDCAT

Nageezi Gallup

11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA

8-23N-8W NMPM

12. COUNTY OR PARISH 13. STATE

San Juan

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different formation. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

BCO, Inc.

3. ADDRESS OF OPERATOR

135 Grant Ave. Santa Fe, New Mexico 87501

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

1960' FEL 2080' FSL Sec 8 T23N R8W NMPM

14. PERMIT NO.

15. ELEVATIONS (Show whether dr., rt., cr., etc.)

GR 6857

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PERMITS OR ALTER CASING

FRACURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

XX

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and pertinent to this work.)

4-20-83 Set RBP at 4900'

4-21-83 Determined well has hole in the casing between 3657'-3672'. Advised Ken Townsend with BLM that we intended to repair same with cement on 4-22-83 at 8:00 a.m.

4-22-83 Set packer at 3348'. Repaired hole in casing with 500 sacks class H 2% CaCl₂ 5/10% CFR-2 cement. Final squeeze pressure 1500 pounds.

4-28-83 to 4-29-83 Drilled cement. Pressure tested at 920#'s and held. Displaced water in hole with KCL water.

5-2-83 to 5-5-83 Removed B.P. Swabbed well. Ran pump and rods and placed well back in production.

18. I hereby certify that the foregoing is true and correct

SIGNED

Harry R. Boyle

TITLE

President

DATE

5/6/83

(This space for Federal or State use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

NMDC