

7. Method of Handling Waste Disposal

Waste will be buried in the reserve pit on completion of the well. The reserve pit will be backfilled. Toilet facilities will be provided.

8. Ancillary Facilities

No camps or airstrips will be used.

9. Diagram of Well Location

See attachment. A 2'-3' cut will be needed on the south edge of the location.

10. Plans for Restoration to Surface

The surface will be restored and reseeded as directed by the Bureau of Land Management.

11. Other Information

Impact on the environment will be minimal. The access road and well location is sparsely vegetated and minimal trees and sage will be disturbed.

12. Operators Representative

Minerals Management, Inc., 501 Airport Dr., Suite 105, Farmington, New Mexico 87401.

13. Certification

I hereby certify that I, or persons under my direct supervision, have inspected the proposed drillsite and access route; that I am familiar with the conditions which presently exist; that the statements made in this plan are, to the best of my knowledge, true and correct; and that the work associated with the operations proposed herein will be performed by Filon Exploration Corporation and its contractors and sub-contractors in conformity with this plan and the terms under which it is approved.

8-4-76
Date

J. Arnold Smith Area Manager

Minerals Management Inc.
Company

AUG 6 1976