



STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT  
OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE

BRUCE KING  
GOVERNOR

LARRY KEHOE  
SECRETARY

1000 RIO BRAZOS ROAD  
AZTEC, NEW MEXICO 87410  
(505) 334-6178

November 24, 1980

Mr. H. D. Hollingsworth  
Dome Petroleum Corporation  
501 Airport Drive  
Farmington, New Mexico 87401

Re: Dome Petroleum Corporation  
Santa Fe 20 #2  
F-20-21N-8W

Dear Holly:

On November 20, 1980, Mr. Gholson and I made an inspection of the above well and lease. We found the operations in violation of several provisions of Order R-6220:

1. There was no gauge or leak detection device installed on the well annulus. The two valves on the annulus were frozen shut and could not be opened.
2. The injection system was operating at approximately 1500 psi in violation of the 1155 psi limitation.

Other problems we found on inspection were as follows:

1. Lack of warning signs about poisonous gas.
2. An oil spill at the #3 well which will require notification as per Rule 116.

You are hereby directed to take immediate action to correct the violations. Please make arrangements with this office to inspect the well and lease after the violations are corrected.

If you have any questions, please contact this office.

Yours truly,

Frank T. Chavez  
District Supervisor

xc: Reading File  
UIC File  
Mr. Ernest Padilla, General Counsel

FTC:no