Office	State	of New Mo	exico	1	F	orm C-103
District I	Energy, Minerals and Natural Resources				Revised March 25, 1999	
1625 N. French Dr., Hobbs, NM 87240			WELL API NO.			
District II 811 South First, Artesia, NM 87210 OIL CONSERVATION DIVISION			30-045-22531			
District III	and thou, the color			5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410				STATE	FEE	X
District IV	Santa	Fe, NM-8	7505	6. State Oil &	Gas Lease No	
2040 South Pacheco, Santa Fe, NM 87505						
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUGBACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" FORMS (D) LESS				7. Lease Name or Unit Agreement Name: Santa Fe H 20 (7840)		
Oil Well Gas Well	Other: SWD					
2. Name of Operator		_	What have	8. Well No		
Synergy Operating LLC		ann C	ON. DIV.	2		
3. Address of Operator	ator Street 14		ment. 3	9. Pool name or Wildcat		
P.O.Box 5513, Farmington, NM 8	1gton, NM 87499			SWD: Morrison Bluff Entrada (96162)		
4. Well Location						
Unit Letter F : 2	150feet from the	North_	line and19	80feet fro	m the <u>West</u>	line
Section 20	m1.'	2131	D 0111		_	
Section 20	Township		Range 8W	NMPM	San Juan	County
10	,		R, RKB, RT, GR, etc.	)		
6568' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
11. Check Appro	opriate Box to I	naicate Na				
NOTICE OF INTER		—		SEQUENT <u>R</u> I		
PERFORM REMEDIAL WORK D	ug and abando	ον []	REMEDIAL WORK		ALTERING	CASING $\square$
TEMPORARILY ABANDON   CH	IANGE PLANS		COMMENCE DRIL	LING OPNS.	PLUG AND	. <b>X</b>
	JLTIPLE DMPLETION		CASING TEST AN	_	ABANDONI	MENT
	MIPLETION		CEMENT JOB			
OTHER:			OTHER:			
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion						
of starting any proposed work). SE or recompilation.	E RULE 1103. Fo	r Multiple C	Completions: Attach	wellbore diagran	n of proposed c	ompletion
of starting any proposed work). SE or recompilation. 7/8/99:	E RULE 1103. Fo	r Multiple C	Completions: Attach	wellbore diagran	n of proposed c	ompletion
of starting any proposed work). SE or recompilation. 7/8/99: MI RU Key Energy rig #8.	E RULE 1103. Fo	r Multiple C	Completions: Attach	wellbore diagran	n of proposed c	ompletion
of starting any proposed work). SE or recompilation. 7/8/99: MI RU Key Energy rig #8. 7/13/99:	E RULE 1103. Fo	r Multiple C	Completions: Attach	wellbore diagran	n of proposed c	ompletion
of starting any proposed work). SE or recompilation. 7/8/99: MI RU Key Energy rig #8. 7/13/99: TOOH, laying down 151-Jts 3-1/2" tbg.	E RULE 1103. Fo	r Multiple C	Completions: Attach	wellbore diagran	n of proposed c	ompletion
of starting any proposed work). SE or recompilation. 7/8/99: MI RU Key Energy rig #8. 7/13/99: TOOH, laying down 151-Jts 3-1/2" tbg. 7/14/99:	E RULE 1103. Fo	r Multiple C			n of proposed c	
of starting any proposed work). SE or recompilation. 7/8/99: MI RU Key Energy rig #8. 7/13/99: TOOH, laying down 151-Jts 3-1/2" tbg. 7/14/99: TIH w/ 7" CIBP, picking up, 2-3/8 " tbg	E RULE 1103. Fo	r Multiple C	.740' & circ hole w/		n of proposed c	
of starting any proposed work). SE or recompilation. 7/8/99: MI RU Key Energy rig #8. 7/13/99: TOOH, laying down 151-Jts 3-1/2" tbg. 7/14/99: TIH w/ 7" CIBP, picking up, 2-3/8 " tbg Plug #1: Spot 19-sxs Cl 'B" cmt from 4	E RULE 1103. Fo , set CIBP @ 4746 746-4646' inside 7	r Multiple C  '. PUH to 4  "' Csg. PUF	.740' & circ hole w/ I to 4507'.		n of proposed c	
of starting any proposed work). SE or recompilation. 7/8/99: MI RU Key Energy rig #8. 7/13/99: TOOH, laying down 151-Jts 3-1/2" tbg. 7/14/99: TIH w/ 7" CIBP, picking up, 2-3/8 " tbg Plug #1: Spot 19-sxs Cl 'B" cmt from 4 Plug #2: Spot 32-sxs Cl 'B' cmt from 4	E RULE 1103. Fo , set CIBP @ 4746 746-4646' inside 7	r Multiple C  '. PUH to 4  "' Csg. PUF	.740' & circ hole w/ I to 4507'.		n of proposed c	
of starting any proposed work). SE or recompilation. 7/8/99: MI RU Key Energy rig #8. 7/13/99: TOOH, laying down 151-Jts 3-1/2" tbg. 7/14/99: TIH w/ 7" CIBP, picking up, 2-3/8 " tbg Plug #1: Spot 19-sxs Cl 'B" cmt from 4 Plug #2: Spot 32-sxs Cl 'B' cmt from 4. 7/15/99:	E RULE 1103. Fo , set CIBP @ 4746 746-4646' inside 7 507-4345' inside 7	r Multiple C  '. PUH to 4 "' Csg. PUH " Csg. PUH	.740' & circ hole w/ I to 4507'. I to 3395'. SION.		n of proposed c	
of starting any proposed work). SE or recompilation.  7/8/99: MI RU Key Energy rig #8.  7/13/99: TOOH, laying down 151-Jts 3-1/2" tbg.  7/14/99: TIH w/ 7" CIBP, picking up, 2-3/8 " tbg Plug #1: Spot 19-sxs Cl 'B" cmt from 4 Plug #2: Spot 32-sxs Cl 'B' cmt from 4:  7/15/99: Plug #3: Spot 28-sxs Cl 'B' cmt from 3:	E RULE 1103. Fo , set CIBP @ 4746 746-4646' inside 7 507-4345' inside 7 393-3243' inside 7	". PUH to 4" " Csg. PUH " Csg. PUH " Csg. PUH	.740' & circ hole w/ I to 4507'. I to 3395'. SION.		n of proposed c	
of starting any proposed work). SE or recompilation.  7/8/99: MI RU Key Energy rig #8.  7/13/99: TOOH, laying down 151-Jts 3-1/2" tbg.  7/14/99: TIH w/ 7" CIBP, picking up, 2-3/8 " tbg Plug #1: Spot 19-sxs Cl 'B" cmt from 4  Plug #2: Spot 32-sxs Cl 'B' cmt from 4:  7/15/99: Plug #3: Spot 28-sxs Cl 'B' cmt from 3: Plug #4: Spot 28-sxs Cl 'B' cmt from 89:	E RULE 1103. Fo , set CIBP @ 4746 746-4646' inside 7 507-4345' inside 7 393-3243' inside 7 95-742'. PUH to 2	". PUH to 4 "" Csg. PUH " Csg. PUH " Csg. PUH	.740' & circ hole w/ I to 4507'. I to 3395'. SION. I to 895'.	FW. Pressure Te	n of proposed c	, held OK.
of starting any proposed work). SE or recompilation.  7/8/99: MI RU Key Energy rig #8.  7/13/99: TOOH, laying down 151-Jts 3-1/2" tbg.  7/14/99: TIH w/ 7" CIBP, picking up, 2-3/8 " tbg Plug #1: Spot 19-sxs Cl 'B" cmt from 4.  Plug #2: Spot 32-sxs Cl 'B' cmt from 4.  7/15/99: Plug #3: Spot 28-sxs Cl 'B' cmt from 3: Plug #4: Spot 28-sxs Cl 'B' cmt from 8.  Plug #5: Spot 53-sxs Cl 'B' cmt from 2'	e RULE 1103. Fo , set CIBP @ 4746 746-4646' inside 7 507-4345' inside 7 393-3243' inside 7 95-742'. PUH to 2 78'-Surface. TOO	". PUH to 4 " Csg. PUH " Csg. PUH " Csg. PUH " Csg. PUH HT8'. H. ND BOB	.740' & circ hole w/ I to 4507'. I to 3395'. SION. I to 895'.	FW. Pressure Te	n of proposed c	, held OK.
of starting any proposed work). SE or recompilation.  7/8/99: MI RU Key Energy rig #8.  7/13/99: TOOH, laying down 151-Jts 3-1/2" tbg.  7/14/99: TIH w/ 7" CIBP, picking up, 2-3/8 " tbg Plug #1: Spot 19-sxs Cl 'B" cmt from 4  Plug #2: Spot 32-sxs Cl 'B' cmt from 4:  7/15/99: Plug #3: Spot 28-sxs Cl 'B' cmt from 3: Plug #4: Spot 28-sxs Cl 'B' cmt from 89:	e RULE 1103. Fo , set CIBP @ 4746 746-4646' inside 7 507-4345' inside 7 393-3243' inside 7 95-742'. PUH to 2 78'-Surface. TOO	". PUH to 4 " Csg. PUH " Csg. PUH " Csg. PUH " Csg. PUH HT8'. H. ND BOB	.740' & circ hole w/ I to 4507'. I to 3395'. SION. I to 895'.	FW. Pressure Te	n of proposed c	, held OK.
of starting any proposed work). SE or recompilation. 7/8/99: MI RU Key Energy rig #8. 7/13/99: TOOH, laying down 151-Jts 3-1/2" tbg. 7/14/99: TIH w/ 7" CIBP, picking up, 2-3/8 " tbg Plug #1: Spot 19-sxs Cl 'B" cmt from 4. Plug #2: Spot 32-sxs Cl 'B" cmt from 4. 7/15/99: Plug #3: Spot 28-sxs Cl 'B' cmt from 3. Plug #4: Spot 28-sxs Cl 'B' cmt from 8. Plug #5: Spot 53-sxs Cl 'B' cmt from 2. w/ 12-sxs Cl 'B' cmt. RD Key Energy ri	e RULE 1103. Fo , set CIBP @ 4746 746-4646' inside 7 507-4345' inside 7 393-3243' inside 7 95-742'. PUH to 2 78'-Surface. TOO ig #8. Install P&A	". PUH to 4 " Csg. PUH " Csg. PUH " Csg. PUH 278". H. ND BOF marker.	740' & circ hole w/ H to 4507'. I to 3395'. SION. I to 895'. P. Dig cellar, cut-off	FW. Pressure Te	n of proposed c	, held OK.
of starting any proposed work). SE or recompilation.  7/8/99: MI RU Key Energy rig #8.  7/13/99: TOOH, laying down 151-Jts 3-1/2" tbg.  7/14/99: TIH w/ 7" CIBP, picking up, 2-3/8 " tbg Plug #1: Spot 19-sxs Cl 'B" cmt from 4.  Plug #2: Spot 32-sxs Cl 'B' cmt from 4.  7/15/99: Plug #3: Spot 28-sxs Cl 'B' cmt from 3: Plug #4: Spot 28-sxs Cl 'B' cmt from 8.  Plug #5: Spot 53-sxs Cl 'B' cmt from 2'	e RULE 1103. Fo , set CIBP @ 4746 746-4646' inside 7 507-4345' inside 7 393-3243' inside 7 95-742'. PUH to 2 78'-Surface. TOO ig #8. Install P&A	". PUH to 4 " Csg. PUH " Csg. PUH " Csg. PUH 278". H. ND BOF marker.	740' & circ hole w/ H to 4507'. I to 3395'. SION. I to 895'. P. Dig cellar, cut-off	FW. Pressure Te	n of proposed c	, held OK.
of starting any proposed work). SE or recompilation. 7/8/99: MI RU Key Energy rig #8. 7/13/99: TOOH, laying down 151-Jts 3-1/2" tbg. 7/14/99: TIH w/ 7" CIBP, picking up, 2-3/8 " tbg Plug #1: Spot 19-sxs Cl 'B" cmt from 4. Plug #2: Spot 32-sxs Cl 'B" cmt from 4. 7/15/99: Plug #3: Spot 28-sxs Cl 'B' cmt from 3. Plug #4: Spot 28-sxs Cl 'B' cmt from 8. Plug #5: Spot 53-sxs Cl 'B' cmt from 2. w/ 12-sxs Cl 'B' cmt. RD Key Energy ri	e RULE 1103. Fo , set CIBP @ 4746 746-4646' inside 7 507-4345' inside 7 393-3243' inside 7 95-742'. PUH to 2 78'-Surface. TOO ig #8. Install P&A	". PUH to 4 " Csg. PUH " Csg. PUH " Csg. PUH 278". H. ND BOF marker.	740' & circ hole w/ H to 4507'. I to 3395'. SION. I to 895'. P. Dig cellar, cut-off	FW. Pressure Te FWH 3' below Go	est Csg to 500#,	, held OK.
of starting any proposed work). SE or recompilation.  7/8/99: MI RU Key Energy rig #8.  7/13/99: TOOH, laying down 151-Jts 3-1/2" tbg.  7/14/99: TIH w/ 7" CIBP, picking up, 2-3/8 " tbg Plug #1: Spot 19-sxs Cl 'B" cmt from 4.  Plug #2: Spot 32-sxs Cl 'B' cmt from 4.  7/15/99: Plug #3: Spot 28-sxs Cl 'B' cmt from 8.  Plug #4: Spot 28-sxs Cl 'B' cmt from 2.  w/ 12-sxs Cl 'B' cmt. RD Key Energy ri  I hereby certify that the information above SIGNATURE	set CIBP @ 4746 746-4646' inside 7 507-4345' inside 7 393-3243' inside 7 95-742'. PUH to 2 78'-Surface. TOO ig #8. Install P&A	". PUH to 4 " Csg. PUH " Csg. PUH " Csg. PUH " Csg. PUH T8'. H. ND BOI marker.	740' & circ hole w/ H to 4507'. H to 3395'. SION. H to 895'. P. Dig cellar, cut-off	FW. Pressure Te FWH 3' below Ge and belief.	n of proposed construction of proposed constru	op off csg
of starting any proposed work). SE or recompilation.  7/8/99: MI RU Key Energy rig #8.  7/13/99: TOOH, laying down 151-Jts 3-1/2" tbg.  7/14/99: TIH w/ 7" CIBP, picking up, 2-3/8 " tbg Plug #1: Spot 19-sxs Cl 'B" cmt from 4.  Plug #2: Spot 32-sxs Cl 'B" cmt from 4.  7/15/99: Plug #3: Spot 28-sxs Cl 'B' cmt from 3.  Plug #4: Spot 28-sxs Cl 'B' cmt from 8.  Plug #5: Spot 53-sxs Cl 'B' cmt from 2.  w/ 12-sxs Cl 'B' cmt. RD Key Energy ri  I hereby certify that the information above  SIGNATURE  Type or print name  Glen O.	set CIBP @ 4746 746-4646' inside 7 507-4345' inside 7 393-3243' inside 7 95-742'. PUH to 2 78'-Surface. TOO ig #8. Install P&A	". PUH to 4 " Csg. PUH " Csg. PUH " Csg. PUH " Csg. PUH T8'. H. ND BOI marker.	740' & circ hole w/ H to 4507'. H to 3395'. SION. H to 895'. P. Dig cellar, cut-off	FW. Pressure Te FWH 3' below Ge and belief.	est Csg to 500#,	op off csg
of starting any proposed work). SE or recompilation.  7/8/99: MI RU Key Energy rig #8.  7/13/99: TOOH, laying down 151-Jts 3-1/2" tbg.  7/14/99: TIH w/ 7" CIBP, picking up, 2-3/8 " tbg Plug #1: Spot 19-sxs Cl 'B" cmt from 4.  Plug #2: Spot 32-sxs Cl 'B' cmt from 4.  7/15/99: Plug #3: Spot 28-sxs Cl 'B' cmt from 8.  Plug #4: Spot 28-sxs Cl 'B' cmt from 2.  w/ 12-sxs Cl 'B' cmt. RD Key Energy ri  I hereby certify that the information above SIGNATURE	set CIBP @ 4746 746-4646' inside 7 507-4345' inside 7 393-3243' inside 7 95-742'. PUH to 2 78'-Surface. TOO ig #8. Install P&A	". PUH to 4 " Csg. PUH " Csg. PUH " Csg. PUH 178'. H. ND BOH marker.	.740' & circ hole w/ H to 4507'. H to 3395'. SION. H to 895'. P. Dig cellar, cut-off est of my knowledge Operations Mar	FW. Pressure Te FWH 3' below Ge and belief.	n of proposed construction of proposed constru	op off csg
of starting any proposed work). SE or recompilation.  7/8/99: MI RU Key Energy rig #8.  7/13/99: TOOH, laying down 151-Jts 3-1/2" tbg.  7/14/99: TIH w/ 7" CIBP, picking up, 2-3/8 " tbg Plug #1: Spot 19-sxs Cl 'B" cmt from 4.  Plug #2: Spot 32-sxs Cl 'B" cmt from 4.  7/15/99: Plug #3: Spot 28-sxs Cl 'B' cmt from 3.  Plug #4: Spot 28-sxs Cl 'B' cmt from 8.  Plug #5: Spot 53-sxs Cl 'B' cmt from 2.  w/ 12-sxs Cl 'B' cmt. RD Key Energy ri  I hereby certify that the information above  SIGNATURE  Type or print name  Glen O.	set CIBP @ 4746 746-4646' inside 7 507-4345' inside 7 393-3243' inside 7 95-742'. PUH to 2 78'-Surface. TOO ig #8. Install P&A	". PUH to 4 " Csg. PUH " Csg. PUH " Csg. PUH 178'. H. ND BOH marker.	.740' & circ hole w/ H to 4507'. H to 3395'. SION. H to 895'. P. Dig cellar, cut-off est of my knowledge Operations Mar	FW. Pressure Te FWH 3' below Ge and belief.	est Csg to 500#.  round Level. T  DATE 7/elephone No.	op off csg
of starting any proposed work). SE or recompilation.  7/8/99: MI RU Key Energy rig #8.  7/13/99: TOOH, laying down 151-Jts 3-1/2" tbg.  7/14/99: TIH w/ 7" CIBP, picking up, 2-3/8 " tbg Plug #1: Spot 19-sxs Cl 'B" cmt from 4.  Plug #2: Spot 32-sxs Cl 'B" cmt from 4.  7/15/99: Plug #3: Spot 28-sxs Cl 'B' cmt from 3.  Plug #4: Spot 28-sxs Cl 'B' cmt from 8.  Plug #5: Spot 53-sxs Cl 'B' cmt from 2.  w/ 12-sxs Cl 'B' cmt. RD Key Energy ri  I hereby certify that the information above  SIGNATURE  Type or print name  Glen O.  (This space for State use)	set CIBP @ 4746 746-4646' inside 7 507-4345' inside 7 393-3243' inside 7 95-742'. PUH to 2 78'-Surface. TOO ig #8. Install P&A	". PUH to 4 " Csg. PUH " Csg. PUH " Csg. PUH 178'. H. ND BOH marker.	740' & circ hole w/ H to 4507'. H to 3395'. SION. H to 895'. P. Dig cellar, cut-off	FW. Pressure Te FWH 3' below Ge and belief.	n of proposed construction of proposed constru	op off csg