

COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Dome Petroleum Corporation		8. Farm or Lease Name Santa Fe 6-20-21-8
3. Address of Operator %Minerals Management Inc., Suite 105, 501 Airport Drive, Farmington, New Mexico 87401		9. Well No. 6
4. Location of Well UNIT LETTER B 990 FEET FROM THE north LINE AND 2310 FEET FROM THE east LINE, SECTION 20 TOWNSHIP 21N RANGE 8W NMPM.		10. Field and Pool, or Wildcat Snake Eyes Entrada
15. Elevation (Show whether DF, RT, GR, etc.) 6554' GR 6566' KB		12. County San Juan

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	


17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Operator intends to plug and abandon well as follows:

Plug No. 1	5510'-5710'	(200')	75	sx
Plug No. 2	4400'-4550'	(150')	75	sx
Plug No. 3	3240'-3390'	(150')	70	sx
Plug No. 4	2370'-2520'	(150')	70	sx
Plug No. 5	800'-952'	(150')	60	sx
Plug No. 6	185'-285'	(100')	35	sx
Plug No. 7	0'-30'	(30')	15	sx

Abandonment Marker will be erected. Location will be restored.
Reserve pit fenced.

CONFIDENTIAL



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Area Manager
Minerals Management Inc. DATE July 13, 1977

Original Signed By A. B. Hendrick
APPROVED BY _____ TITLE _____ DATE 7/13/77

CONDITIONS OF APPROVAL, IF ANY: