UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

DEPARTMENT OF THE INTERIOR	6. IF INDIAN, ALLOTTEE OR TRIBE NAME 7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME Midway			
GEOLOGICAL SURVEY				
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different				
reservoir. Use Form 9–331–C for such proposals.)				
2. NAME OF OPERATOR Lan Juan Venture	9. WELL NO.			
Tenneco Oil Company 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Undes. Chacra			
P.O. Box 3249, Englewood, CO 80155 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 22, T22N, R8W			
AT SURFACE: 990' FSL, 18050' FWL AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	12. COUNTY OR PARISH 13. STATE San Juan New Mexico			
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	14. API NO.			

(NOTE: Report results of multiple completion or zone

charge on Form 9-330.)

5. LEASE

3. ADDRESS OF OPERATOR P.O. Box 3249, Englewood, CO 80155 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 1850 990' FSL, 18050' FWL AT SURFACE: AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE. REPORT, OR OTHER DATA 15. ELEVATIONS (SHOW DF, KDB, AND WD)

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES U. S. GEOLOGICAL SURVEY ABANDON* FARMINGTON, N. M. (other)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

In accordance with the request by the U.S.G.S., Tenneco proposes to plug and abandon the above referenced well as detailed in the procedure attached.

Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct LITLE Production Analyst DATE 1/22/82 for Federal or State office use) APPROVED BY CONDITIONS OF

FOR JAMES F. SIMS DISTRICT ENGINEER

*See Instructions on Reverse Side

FEV2E	Midway	
WELL NO.	3	

7	*OD	23	LB,_		csc.w/	 S>
TÒC O				•		•
TOC P	surfa	ace		<u> </u>		

4-1/2	00	9.5	_LE,	csg.	H/	s
TOC @				·•	_	

DETAILED PROCEDURE

- 1. MIRUSU.
- 2. RIH w/2-3/8" tbg & bit.
- 3. CO hole to PBTD.
- 4. Set cmt plug from PBTD to surface w/Class 'B' neat cmt. (±150 sx). * See attached modifications.
- 5. RDMOSU.
- 6. Cut off csg & install P&A marker.
- 7. Clean up location, fill pits and re-seed.

401

U. S. GEOLOGICAL SURVEY Drawer 600 Farmington, New Mexico 87499-00600

Attachment to Notice of Intention to Abandon

Re: Permanent Abandonment

Well: 3 Midway

CONDITIONS OF APPROVAL

Plugging operations authorized are subject to the attached "General Requirements for Permanent Abanconment of Wells on Federal Leases."

- 2. The Farmington office (telephone (505) 325-4572) is to be notified in sufficient time for a representative to witness all plugging operations.
- Blowout prevention equipment is required.
- 4. In addition to normal filling of pits and cleanup of location, additional surface restoration work may be required, i.e. ripping of pad and/or access road, reseeding, etc. We have asked the Bureau of Land Management for the surface restoration requirements for this well and we should be able to furnish you these requirements within 30 days. After plugging the well and before making final clean-up, you should contact this office unless you have already been advised as to what additional surface restoration work is required.
- 5. The following modifications to your plugging program are to be made (when applicable):
 - a) Perforate 4½" casing at 450' and spot cement plug inside and antside casing from 450' to 350' to cover Fruitland top.
 - b) Perforate 4½" casing at 90' and spot coment plug inside and autside casing from 90' to surface to cover surface casing shoe.

Office Hours: 7:30 A.M. to 4:15 P.M.