

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)- Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. NM 8902
2. NAME OF OPERATOR Dugan Production Corp.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Box 208, Farmington, NM 87401		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1650' FSL - 1770' FEL		8. FARM OR LEASE NAME Billie
14. PERMIT NO.		9. WELL NO. A1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6645' GR		10. FIELD AND POOL, OR WILDCAT Wildcat
		11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA Sec 35 T22N R8W
		12. COUNTY OR PARISH 13. STATE San Juan NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
(Other)	<input type="checkbox"/>	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Request permission to plug and abandon this well in the following manner:

1. Fill 2-7/8" O.D., 6.5#, J-55, 8 Rd, EUE tubing for casing from T.D. 900' to surface using 25 sx of cement.
2. Install permanent dry hole monument.
3. Fill all pits.
4. Clean well location of all equipment, pipe, junk, and trash.
5. Accomplish surface restoration as specified by the surface management agency or land owner.
6. Cut or remove tie-downs.

18. I hereby certify that the foregoing is true and correct

SIGNED Sherman E. Dugan
Sherman E. Dugan


TITLE Agent

DATE 2-1-82

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE

*See Instructions on Reverse Side
NMOCC

U. S. GEOLOGICAL SURVEY
Drawer 600
Farmington, New Mexico 87499-00600

Attachment to Notice of
Intention to Abandon

Re: Permanent Abandonment

Well: #1 Billie

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."
2. The Farmington office (telephone (505) 325-4572) is to be notified in sufficient time for a representative to witness all plugging operations.
3. Blowout prevention equipment is required.
4. In addition to normal filling of pits and cleanup of location, additional surface restoration work may be required, i.e. ripping of pad and/or access road, reseeding, etc. We have asked the Surface Management Agency for the surface restoration requirements for this well and we should be able to furnish you these requirements within 30 days. After plugging the well and before making final clean-up, you should contact this office unless you have already been advised as to what additional surface restoration work is required.
5. The following modifications to your plugging program are to be made (when applicable):

*add a braden head squeeze with sufficient
cement to fill the 2 7/8" casing annulus to
a depth of 220 feet*

