er. 3150 ≤ .-e 5er 1983). certy 9 -331)

1 100

UNITED STATES DEPARTMENT OF THE INTERIOR (Other Instructions on re-UNITED STATES

Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO.

Section 24-23N-9W

San Juan


:. FIFVATIONS (Show whether DF, RT, GR, etc.)

BUREAU OF LAND MAI	
SUNDRY NOTICES AND RE	DORTS ON WELLS
WELL X WELL OTHER	JUN 1 1 1927
AME OF OPERATOR	8. FARM OR LEASE NAME
Yates Drilling Company	8. FARM OR LEASE NAME FARMINATION RESULTAGE AND AREA 9. WELL NO.
105 South 4th Street, Artesia, Ne rocartos or well (Report location clearly and in accordance also space 17 below)	W Mexico 88210 10. PIELD AND POOL, OR WILDCAT
2100' FNL & 400' FEL	Wildcat 11. SBC., T., B., M., OR BLK. AND SURVEY OR ARMA

NOTE & OF INTENTION TO		SUBBEQUENT REPORT OF:	
Tall to the Fr	F	WATER SHUT-OFF	REPAIRING WELL
EFIRE:	Maria de DE Colonia FTE	FRACTURE TREATMENT	ALTERING CASING
n ACL	Marketo S.C.	SHOOTING OR ACIDIZING	ABANDONMENT*
Air of F. I	CHANGE BLANC	(Other) Spud Well	X
tar t		(Norm: Report results of a Completion or Recompletion	multiple completion on Well

Spudded 12 1/4" hole at 3:15 P.M., 5-29-87 with Walter's Drilling Company Rig #2. Notified Mark Kelley with the BLM, Farmington, New Mexico.

5-29-87 Ran 7 joints 8 5/8", 24#, J-55 casing set at 280'. 1-Regular guide shoe set at 280'., baffle plate set at 240'. Cemented with 190 sxs. Class "B" with 2% CaCl₂ (yield 1.14, weight 15.6-217 cu.ft.) Compressive strength of cement - 950 PSI in $1\overline{2}$ hrs. PD 8:15 P.M., 5-29-87. Did not bump plug. Circulated 25 sxs. to pit. WOC 13 hrs. Drilled out at 9:15 A.M., 5-30-87. Nippled up and tested to 1000# PSI for 30 minutes, OK. Reduced hole to 7 7/8", drilled plug and resumed drilling.



Toren g. Luchman	TITLE	Production Clerk	AUTETIED FOR 101870
. Star- 107 Federal or State office time.			194 15 184.
THE ACT BY THE HOLD ONE OF APPROVAL, IF ANY	TITLE		DATE
			takmikaron neosonor Anta
			gv Smm

*See Instructions on Reverse Side