

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

SF 078910

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Lindrith Unit

8. FARM OR LEASE NAME

Lindrith Unit

9. WELL NO.

55

10. FIELD AND POOL, OR WILDCAT

So. Blanco Pic. Cliffs

11. SEC. T. R. M. OR S.W. AND
SURVEY OR AREA

Sec. 32, T-24-N, R- 2-W
N.M.P.M.

12. COUNTY OR PARISH 13. STATE

Rio Arriba NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

El Paso Natural Gas Company
FARMINGTON, NEW MEXICO

3. ADDRESS OF OPERATOR

Post Office Box 4289, Farmington, NM 87499

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface 800'S, 1650'W

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, RT, GR, etc.)

7256'GL

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PLUG OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion or Well
Completion or Recuplication Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It is intended to plug and abandon this location in the following manner:

MOL & RU. TIH w/1 1/4" IJ work string and strap. Set @ approximately 3100'. Circulate hole w/25 bbls. 9# mud across perfs. TOOH. Wireline shoot 2 squeeze holes @ 2699' Ojo Alamo. TIH w/1 1/4" tbg & spot 65 sx. cmt. plug from 3199' TD to 2649' to cover perforations, fill annulus and tbg 50' over Ojo Alamo top. Tag plug. TOOH. Fill casing with 15 bbls. 9# mud. Wireline shoot two holes @ 162'. Circulate 55 sx. cement to surface. Cut off wellhead & set dry hole marker.

18. I hereby certify that the foregoing is true and correct

SIGNED

(This space for Federal or State office use)

TITLE Drilling Clerk

DATE

09-18-87

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

*See Instructions on Reverse Side

NMOC

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.