

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/>	7. UNIT AGREEMENT NAME Lindrith Unit
2. NAME OF OPERATOR El Paso Natural Gas Company	8. FARM OR LEASE NAME Lindrith Unit
3. ADDRESS OF OPERATOR Post Office Box 4289, Farmington, NM 87499	9. WELL NO. 55
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 800'S, 1650'W	10. FIELD AND POOL, OR WILDCAT S. Blanco Pic Cliffs
14. PERMIT NO.	11. SEC., T., R., E., M., OR S.W. 1/4, AND SURVEY OR AREA Sec. 32, T-24-N, R-02-W
15. ELEVATIONS (Show whether DP, RT, GR, etc.) 7256' CL	12. COUNTY OR PARISH N. M. D. M.
	13. STATE Rio Arriba NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

REEL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.*

10-14-87

MOL&RU. Run wireline. Tag TD @ 3199'. TIH w/1 1/4" work string to 3199'. Circ. 25 bbls. 9# gel to surface. TOOH w/workstring. Shot 2 holes @ 2699'. TIH w/work string. Pump 70 sx (14 bbls) cmt. plug from 3199-2620'. TOOH. WOC. TIH w/workstring. Tag cmt @ 2620'. Shot 2 holes @ 162'. Circ. gel out bradenhead. Pump 60 sx (12 bbls) cmt, circulated out bradenhead. Cut off wellhead and set dry hole marker.

RECEIVED
OCT 20 1987

OCT -3 PM 2:15

FARMINGTON REGISTRATION AREA
FARMINGTON, NEW MEXICO

Approved as to plugging
Liability under bond for
surface restoration & safety

RECEIVED

OCT 20 1987

OIL CON. DIV
DIST. 2

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Regulatory Affairs ()

DATE

09-30-88

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

NMOCC

*See Instructions on Reverse Side

OCT 27 1987

James E. Edwards Jr.
FARMINGTON, NEW MEXICO