	TiigtOH	Agricus Santon Santon (m. 12. Santon)		
l Robert Ramire		NITED STATES	SUBMIT IN ARIPLIC	Form approved.
(May (933)			. ∩ • h = e + - e	Budje: Bureso-No. 42-R142
		INT OF THE INTER	KIUK verse sicer	5. LEASE DESIGNATION AND SERVE NO.
	GEC	DLOGICAL SURVEY		SF-078534
CLIN	יחשע איחדוכי	S AND REPORTS	ON WELLS	6. IF INDIAN, ALIGHES OR TEISTING
(Do not ase tale	TH "APPLICATIO	to drill or to deepen or ply ON FOR PERMIT—" for stick	Ponto (L)	
1.			2007	7. UNIT AGREEMENT NAME
OIL X CAS	П		JAN 77 1983	
2. NAME OF OPERATOR	U OTHER		JAIA	8. FARM OR LEISE NAME
			U. S. GEO COUCH N. M.	D. 11 D
BCO, Inc.	· · · · · · · · · · · · · · · · · · ·		GEOLOGIAL M. M.	Bobby B
3. ADDRESS OF OPERATO	в.		U. S. Cal	9. WELL NO.
135 Grant Ave.	Santa Fe, No	ew Mexico 87501	•	2
4. EDCATION OF WELL (Report location clear	ly and in accordance with a	ny State requirements.*	10. FIELD AND POHL, OS WILDCAT
See also space 17 bel At surface	Escrito Gallup			
590' FNL and 1650' FEL Sec 31 T24N R6W				11. SEC., T., E., M. OR BLE, AND
Jyo FML and	TOTO PER S	SEC 31 124N ROW		BURYEY OR ARMA
				21 00/11 0611 10011
			•	31 T24N R6W NMPM
14. PERMIT NO.	1	15. ELEVATIONS (Show whether	DF, RT, GR, elc.)	12. COUNTY OR: PARISH 13. STATE
		GR 6734		Rio Arriba N.M.
	<u> </u>			01 0
16.	Check Appro	opriate Box to Indicate	Nature of Notice, Report,	, or Other Data
	NOTICE OF INTENTION	x TO:	1 8	UBSEQUENT REPORT_OF:-
TEST WATER SHUT-C	PCLI	L OB ALTER CASINO	WATER SHUT-OFF	AZPAIRING WELL
FRACTURE TREAT	71CT.	TIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASINO
SHOOT OR ACIDIZE	ABAT	NDON*	SHOOTING OR ACIDIZIN	G ABANDONMENT
NEPAIR WELL	XX CHA:	NGE PLANS	(Other)	
(Other)	L-served	ļ 	(Note: Report	results of multiple completion on Well
				ecompletion Report and Log form.)
proposed work. It	[well is directionall;	ons (Clearly state all perting drilled, give subsurface lo	ent details, and give pertinent cations and measured and true	dates, including estimated date of sucting an verticul depths for all markers and zon-
nent to this work.)	•	`		
		-	e. Intend to set RE	<u>-</u>
perfs (54	74-5504) and	then use a packer	to find the hole in	the casing. Intend
to repair	said hole wi	th cement, let cer	ment set for at leas	t 72 hours, then
drill out	cement, remo	ove RBP, swab well	and place back in p	roduction.
	•	•	•	
The above	work was ver	bally approved by	Ken Townsend with t	he Bureau of Land
	t on this dat			
1 Edita Semen	- on chits dat	,		
		•		
			ger-	
				The state of the s
		•		
•			FEB 4 ~	1983
				_
•		40	OIL CON	I DIV
			DIST.	3
a freeze.		•		
1	**************************************			
18. I bereby certif that	the foregoing is tru	ie and correct		
2	RAI		President	DATE: 1-28-83
SIGNED TARY	11 Veget	TITLE	11631delle	DATE 1-20-03
(This space for Fede	tal or State place u	se)		
1 4	in 1003	-		•
APPROVED BY	1M. Jam	TITLE		DATE
CONDITIONS OF A	PPROVAL, IT ANY	:		