

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR
Texaco Inc. (303) 565-8401

3. ADDRESS OF OPERATOR
P. O. Box EE, Cortez, CO. 81321

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
SE $\frac{1}{4}$ SE $\frac{1}{4}$ Sec. 25, T24N, R2W

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, RT, GR, etc.)
7536' KB

5. LEASE DESIGNATION AND SERIAL NO.
SF-080500

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Anderson 'A'

9. WELL NO.
2

10. FIELD AND POOL, OR WILDCAT
So. Blanco P.C.

11. SEC., T., R., M., OR BLK. AND SURVEY OR ARMA
Sec. 25, T24N, R2W

12. COUNTY OR PARISH
Rio Arriba

13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
(Other)	<input type="checkbox"/>	(NOTE: Report results of multiple completion on Well Completion or Reconpletion Report and Log form.)	
PULL OR ALTER CASING	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
ABANDON*	<input checked="" type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Texaco proposes to permanently plug and abandon the subject well using the following procedure.

- 1) Set cement retainer @ 3200'.
- 2) Pump 25 sx 50/50 Pozmix cement into retainer to provide plug for perforations and Fruitland formation (Top of primary cement at 3200').
- 3) Perforate a 4-way squeeze shot at 3153 and place a 90 sx cement plug, inside and out, 2935-3153. (Ojo Alamo).
- 4) Perforate a 4-way squeeze shot at 260 and place a 110 sx cement plug, inside and out, from surface to 260' (surface casing shoe and surface plug).
- 5) 9.2 ppg brine-based mud shall be left in all casing volume not occupied by cement.

RECEIVED

DEC 23 1987

OIL & GAS

DEC. 8

18. I hereby certify that the foregoing is true and correct

SIGNED

Alan A. Kleier

TITLE

AREA SUPERINTENDENT

DATE

12/15/87

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

BLM (4)-LAA-AAK

*See Instructions on Reverse Side

APPROVED

DEC 18 1987

DATE

MANAGER

FARMINGTON RESOURCE AREA