

VAL R. REESE & ASSOCIATES, Inc.

GEOLOGICAL & ENGINEERING CONSULTANTS

PHONE CHAPEL 3-3569

ALBUQUERQUE, NEW MEXICO

LOBBY OF SIMMS BUILDING

January 17, 1961

Mr. Emery Arnold
New Mexico Oil Conservation Commission
1000 Rio Brazos Road
Aztec, New Mexico

Dear Mr. Arnold:

Re: #1-30 Sperling Well
Sec. 30, T-24N, R-6W
Rio Arriba Co., N. M.

In response to your request concerning a deliverability test of the Dakota on the #1-30 Sperling well, I desire to report that presently we are unable to obtain a deliverability test on the Dakota; the reason being that the Dakota side of the well is shut-in. We are in the process of setting a separator and a meter for the Dakota and will compress the gas. As soon as we can get the well into operation, we will schedule a deliverability test.

My delay in answering your request was occasioned by the fact that I thought we would have the well in production prior to this date.

Very truly yours,


Val R. Reese

VRR:hk

