

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved:
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	RECEIVED 17 JUL 85	5. LEASE DESIGNATION AND SERIAL NO. <i>Jicarillo Contract 12</i>
2. NAME OF OPERATOR <i>Mobil Oil Corporation</i>	FARMINGTON RESOURCE AREA FARMINGTON, NEW MEXICO	6. IF INDIAN, ALLOTTEE OR TRIBE NAME <i>Jicarillo Apache</i>
3. ADDRESS OF OPERATOR <i>P.O. Drawer G, Cortez, CO 81321</i>		7. UNIT AGREEMENT NAME <i>-</i>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <i>1650' FNL, 1650' FEL</i>		8. FARM OR LEASE NAME <i>Jicarillo Otero</i>
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) <i>GL: 6607'</i>	9. WELL NO. <i>2</i>
		10. FIELD AND POOL, OR WILDCAT <i>Otero-Gallup</i>
		11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA <i>Sec 28, T24N, R5W</i>
		12. COUNTY OR PARISH <i>Rio Arriba</i>
		13. STATE <i>N. Mex.</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) *Temporarily Abandon*

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

(Other) *X*

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☒

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

7-1-87 MIRU.

7-6-87 Try to unseat pump. Jarred on pump. NU BUP's. Began stripping out of hole w/ tbg and rods.

7-7-87 Fin stripping out of hole with prod equipment. RIH w/ bit and 4-1/2" casing scraper.

7-8-87 Fin RIH w/ bit and scraper. Tagged PBTD @ 6275'. Circ hole w/ 100 bbls water. POOH. RIH w/ RBP and pkr. Set RBP @ 5480'. Located hole in csq 628-644. Hole took 3/4 BPM @ 1400 psi w/ returns up braeden head. POOH w/ tbg and pkr.

7-9-87 RIH w/ tbg and pkr. Set pkr @ 314'. Mixed and pumped 150sx (162 cu.ft) neat Class B cement. Pumped @ 1 BPM, 1200 psi. Displaced w/ 5.7 Bbls water. No returns up braeden head. Released pkr and POOH. RIH w/ open ended tbg. (Continued on attached Sheet)

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

APPROVED
AS AMENDED

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

AREA MANAGER