

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

EOG (New Mexico Inc.)

3. Address and Telephone No.

621 17th St., Suite 1800, Denver, CO 80293 (303) 293-9999

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter B 990 FNL & 1650 FEL

Section 28-T24N-R1W

5. Lease Designation and Serial No.

SF 079352-A

6. If Indian, Allottee or Tribe Name

N/A

7. If Unit or CA, Agreement Designation

N/A

8. Well Name and No.

Harrington Federal #3

9. API Well No.

30-039-05320

10. Field and Pool, or Exploratory Area

Blanco Pictured Cliffs

11. County or Parish, State

Rio Arriba, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☒ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 1) MIRU, install BOP. POH w/1" tbg.
- 2) Set CIBP, above PC zone @ 3020' RKB.
- 3) Run pkr on 2-3/8" tbg, set pkr @ 2940'.
- 4) Perforate Fruitland coal section 2960-66' & 2972-88'.
- 5) Swb/tst Fruitland zones for production - record SITP and AM fluid levels.
- 6) Stimulate coal sections as deemed necessary.
- 7) Swb tst for CBM production.
- 8) Equip for production and turn into sales line. (Run MIT if necessary).

Operator proposes to start this work approx. 9/25/94.

RECEIVED
OCT 2 4 1994

OIL CON. DIST.
DIST. 3

cc: **NMOCC-Aztec**

14. I hereby certify that the foregoing is true and correct

Signed **Connie Smith**

Title **Sr. Engineering Tech.**

Date **8/31/94**

(This space for Federal or State office use)

Approved by **Patricia M Hester**

Acting Chief, Lands and Mineral Resources

Date **OCT 20 1994**

Conditions of approval, if any: