

VAL R. REESE & ASSOCIATES, Inc.

CONSULTING GEOLOGISTS

PHONE 243-3569

ALBUQUERQUE, NEW MEXICO

2820 CENTRAL AVE., S.E.

February 9, 1963

Mr. Emery Arnold
New Mexico Oil Conservation Commission
1000 Rio Brazos Road
Aztec, New Mexico

Dear Mr. Arnold:

As was discussed with you by phone, we were unable to take a GOR test during January on our Mesa 1-25 well, Section 25, Township 24 North, Range 7 West, in the Escrito-Gallup field. The tubing was plugged with paraffin, and the well would not produce. Work has now been completed on the well, and it will be put back on production February 11th. A GOR test will be taken beginning February 13th and the results immediately reported.

Very truly yours,

Lewis C. Jameson

Lewis C. Jameson

LCJ:hk

