

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved,
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

Conto #12

6. IF INDIAN, ALLOTTEE OR TRUST LAND

Lieaville Apache

7. UNIT AGREEMENT NO.

8. FARM OR LEASE NAME

Lieaville etoro

9. WELL NO.

3

10. FIELD AND FOOTAGE (If applicable)

Basin District

11. SEC., T., R., OR QUARTER, AND SURVEY OR AREA

Sec 22, T. 24-N, R. 5-W

12. COUNTY OR PARISH (If applicable)

Wilbarger, Oklahoma

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR

Mobil Oil Corporation

3. ADDRESS OF OPERATOR

Box 623, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

14. PERMIT NO.

Unit D, 290' FULT & 290' FULT, Sec 22, T. 24-N, R. 5-W

15. ELEVATIONS (Show whether LF, RI, GS, etc.)

6481 FT

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONING*

(NOTE: Report results of multiple completion or multiple fracture treatment only at completion of Recombination Report and Log.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugged And Abandoned as Per attached Daily Drilling Report

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE

Director and President

DATE

2-23-72

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

JICARILLA OTERO #3, Basin Dakota Fld, Sec 28, 24N, 5 W, Rio Arriba Co, NM. OBJECTIVE: P&A. AFE 2729 - Mobil Intr 100% - Cost \$7700.

- 8/2/72 Bedford, Inc. RU, kill well, spot 10x plug over perfs, top @ 6660.
- 8/3 Circ mud, pulled 1½ tbg IJ - welded stub to 5½.
- 8/5 Shot 5½ csg @ 4000, did not part, stuck, SD for new explosive.
- 8/7 Shot 5½ csg @ 5750, would not come free, shot @ 3495, came loose pulling 5½.
- 8/8 Pulled 5½ csg, ran tbg to 3500 to spot plug.
- 8/9 Spot 30x plug 3550 - 3450, spot plug PC form 60x 2250 - 2150, pull tbg.
- 8/10 Replace clutch, weld stub 8-5/8 csg.
- 8/11 Set jacks 8-5/8 csg - stuck @ 950, rig to perf Ojo Alamo, perf 4 holes 1950', ran 1½ tbg to 1960, sqz Ojo Alamo w/ 120x, pull tbg.
- 8/12 Set jacks, shot 8-5/8 csg @ 950, pull 8-5/8 csg.
- 8/14/72 Ran 1½ tbg to 1000, spot 60x over 8-5/8 stub, pull tbg to 364 csg shoe surf, spot 60x, pull tbg, 15x plug surf, set marker. P&A 8/14/72.
FINAL REPORT.