

Form 9-331a
(Feb. 1951)

	23	
		X

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe**
Lease No. **NM 019399**
Unit _____

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS JAN 13 1958

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

NOTICE OF INTENTION TO DRILL	X	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 9, 19 57

Well No. **23B** is located **1130** ft. from **N** line and **1175** ft. from **E** line of sec. **23**

SE/4 23
(1/4 Sec. and Sec. No.)

24N 2W
(Twp.) (Range)

N. M. P. M.
(Meridian)

(Field)

Rio Arriba
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is **7330** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

3400' Pictured Cliffs tests. Set 5 5/8 24# casing @ 100: Set 5 1/2 14# casing on top of Pictured Cliffs @ 3260: Fracture treat Pictured Cliffs and complete.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **San Juan Gas Corporation**

Address **300 Shell Bldg.**

Tulsa, Oklahoma

By

Title

Date **10 DECEMBER 1957**

1. Is the Operator the only owner* in the dedicated acreage outlined on the plat below?
Yes ✓ No .

2. If the answer to question one is "no," have the interests of all the owners been consolidated by communitization agreement or otherwise? Yes No . If answer is "yes," Type of Consolidation

3. If the answer to question two is "no," list all the owners and their respective interests below:

REF. GLO Plat dated. 18 DECEMBER 1917

Land Description

KLUULIYU
 JAN 14 1958
 OIL CON. COM.
 DIST. 3

23
 NM-03992
 NM-019399

1175'
 1130'

30 60 90 120 150 180 210 240 270 300 330 360 390 420 450 480 510 540 570 600 630 660 690 720 750 780 810 840 870 900 930 960 990 1020 1050 1080 1110 1140 1170 1200 1230 1260 1290 1320 1350 1380 1410 1440 1470 1500 1530 1560 1590 1620 1650 1680 1710 1740 1770 1800 1830 1860 1890 1920 1950 1980 2010 2040 2070 2100 2130 2160 2190 2220 2250 2280 2310 2340 2370 2400 2430 2460 2490 2520 2550 2580 2610 2640 2670 2700 2730 2760 2790 2820 2850 2880 2910 2940 2970 3000 3030 3060 3090 3120 3150 3180 3210 3240 3270 3300 3330 3360 3390 3420 3450 3480 3510 3540 3570 3600 3630 3660 3690 3720 3750 3780 3810 3840 3870 3900 3930 3960 3990 4020 4050 4080 4110 4140 4170 4200 4230 4260 4290 4320 4350 4380 4410 4440 4470 4500 4530 4560 4590 4620 4650 4680 4710 4740 4770 4800 4830 4860 4890 4920 4950 4980 5010 5040 5070 5100 5130 5160 5190 5220 5250 5280 5310 5340 5370 5400 5430 5460 5490 5520 5550 5580 5610 5640 5670 5700 5730 5760 5790 5820 5850 5880 5910 5940 5970 6000 6030 6060 6090 6120 6150 6180 6210 6240 6270 6300 6330 6360 6390 6420 6450 6480 6510 6540 6570 6600 6630 6660 6690 6720 6750 6780 6810 6840 6870 6900 6930 6960 6990 7020 7050 7080 7110 7140 7170 7200 7230 7260 7290 7320 7350 7380 7410 7440 7470 7500 7530 7560 7590 7620 7650 7680 7710 7740 7770 7800 7830 7860 7890 7920 7950 7980 8010 8040 8070 8100 8130 8160 8190 8220 8250 8280 8310 8340 8370 8400 8430 8460 8490 8520 8550 8580 8610 8640 8670 8700 8730 8760 8790 8820 8850 8880 8910 8940 8970 9000 9030 9060 9090 9120 9150 9180 9210 9240 9270 9300 9330 9360 9390 9420 9450 9480 9510 9540 9570 9600 9630 9660 9690 9720 9750 9780 9810 9840 9870 9900 9930 9960 9990 10000

James P. Lease
Registered Professional
Engineer and/or Land Surveyor.
JAMES P. LEASE

Certificate No. 1463