UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	,	cices and Reports on We	:115	
			5.	Lease Number Jic Contract 12
l. Type of Wel GAS	.1		6.	If Indian, All. or Tribe Name
			7	Jicarilla Apache
2. Name of Ope	rator		_ 7.	Unit Agreement Name
MERIDL				
2 7 1 1 1	1. 17 6 6		8.	Well Name & Number
	hone No. of Opera	i tor [87499 (505) 326-9700	9.	Jicarilla P #12 API Well No.
LO BON 120	o, rarmingcon, Mi	(303) 320-3700	9.	30-039-05357
	Well, Footage, S		10.	Field and Pool
990°FSL, 84	U'FWL, Sec.22, T-	24-N, R-5-W, NMPM	1.1	Ballard Pictured Cliff
			11.	County and State Rio Arriba Co, NM
12. CHECK APPR	OPRIATE BOX TO IN	DICATE NATURE OF NOTIC	F PEROPE OFFICE	Dama
Type of Sub		Type of A		DATA
	ice of Intent	_X_ Abandonment	Change of Pla	ans
		Recompletion	New Construct	cion
X Sub	sequent Report	Plugging Back	Non-Routine	
Fin	al Abandonment	Casing Repair Altering Casing	<pre> Water Shut or Conversion to</pre>	
		Other -	Conversion Co	o injection
	Proposed or Comp	leted Operations		
l3. Describe	-	reted operations		
8-3-95 1	MIRU. ND WH. NU B POOH. TIH w/cm OK. Load hole of pump 41 sx Clas retainer. POOH holes @ 1930'. from Robert Ken TIH to 1980'. Plu sqz holes @ 182 cmt down csg an off WH. Fill cs	OP. PT BOP. TOOH w/115 t retainer, set @ 2246 w/wtr. PT csg to 1000 ss "B" cmt below cmt r. Load hole w/wtr. PT Could not inject into nt, BLM). g #2: pump 29 sx Class 2'. Establish circ out	'. Load tbg w/wtrpsi, OK. Establisetainer, 22 sx Clcsg to 500 psi, Cperfs. (Verbal among the company of the com	th injection. Plug #1: ass "B" cmt above cmt DK. TOOH. TIH, perf 4 so pproval to changes plan 1980'. POOH. TIH, perf 2 #3: pump 60 sx Class " bradenhead. ND BOP. Cut
8-3-95 1 8-4-95 5	MIRU. ND WH. NU B POOH. TIH w/cm OK. Load hole w pump 41 sx Cla: retainer. POOH holes @ 1930'. from Robert Ken TIH to 1980'. Plu sqz holes @ 182 cmt down csg ar off WH. Fill cs released. Well	OP. PT BOP. TOOH w/115 t retainer, set @ 2246 w/wtr. PT csg to 1000 ss "B" cmt below cmt r . Load hole w/wtr. PT Could not inject into nt, BLM). g #2: pump 29 sx Class 2'. Establish circ out nd out bradenhead. Cir sg & install dry hole plugged and abandoned foregoing is true and	'. Load tbg w/wtrpsi, OK. Establisetainer, 22 sx Clcsg to 500 psi, Cperfs. (Verbal among the correct.	c. PT tbg to 2000 psi, th injection. Plug #1: ass "B" cmt above cmt DK. TOOH. TIH, perf 4 sc pproval to changes plan 1980'. POOH. TIH, perf 2 #3: pump 60 sx Class " radenhead. ND BOP. Cut ass "B" cmt. RD. Rig
8-3-95 1 3-4-95 5	MIRU. ND WH. NU B POOH. TIH w/cm OK. Load hole of pump 41 sx Clast retainer. POOH holes @ 1930'. from Robert Ken TIH to 1980'. Plu sqz holes @ 182 cmt down csg an off WH. Fill con released. Well	OP. PT BOP. TOOH w/115 t retainer, set @ 2246 w/wtr. PT csg to 1000 ss "B" cmt below cmt r . Load hole w/wtr. PT Could not inject into nt, BLM). g #2: pump 29 sx Class 2'. Establish circ out nd out bradenhead. Cir sg & install dry hole plugged and abandoned foregoing is true and Title Regulatory A	'. Load tbg w/wtrpsi, OK. Establisetainer, 22 sx Clcsg to 500 psi, Cperfs. (Verbal among the correct. 'B" cmt @ 1725-19 bradenhead. Plugger 1 bbl cmt out be marker w/15 sx Cl 8-4-95.	c. PT tbg to 2000 psi, th injection. Plug #1: ass "B" cmt above cmt DK. TOOH. TIH, perf 4 sc pproval to changes plan 1980'. POOH. TIH, perf 2 #3: pump 60 sx Class " radenhead. ND BOP. Cut ass "B" cmt. RD. Rig
8-3-95 1 3-4-95 5	MIRU. ND WH. NU B POOH. TIH w/cm OK. Load hole of pump 41 sx Clast retainer. POOH holes @ 1930'. from Robert Ken TIH to 1980'. Plu sqz holes @ 182 cmt down csg an off WH. Fill con released. Well	OP. PT BOP. TOOH w/115 t retainer, set @ 2246 w/wtr. PT csg to 1000 ss "B" cmt below cmt r . Load hole w/wtr. PT Could not inject into nt, BLM). g #2: pump 29 sx Class 2'. Establish circ out nd out bradenhead. Cir sg & install dry hole plugged and abandoned foregoing is true and	'. Load tbg w/wtrpsi, OK. Establisetainer, 22 sx Clcsg to 500 psi, Cperfs. (Verbal among the correct. 'B" cmt @ 1725-19 bradenhead. Plugger 1 bbl cmt out be marker w/15 sx Cl 8-4-95.	c. PT tbg to 2000 psi, th injection. Plug #1: ass "B" cmt above cmt DK. TOOH. TIH, perf 4 sc pproval to changes plan 1980'. POOH. TIH, perf 2 #3: pump 60 sx Class " radenhead. ND BOP. Cut ass "B" cmt. RD. Rig

DEGENTED AUG 3 1 1995
OUL GON, DUV.