For ()	m <b>9-</b> Feb. 19	881 a 81)	eti	.on	21
			 g l		

## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Land Office	Senta	ře
Lease No		
Wer	nts-Pe	ierel
Unit		

IOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
OTICE OF INTENTION TO CHANGE PLANS		1
OTICE OF INTENTION TO CHANGE PLANS OTICE OF INTENTION TO TEST WATER SHUT-C		
OTICE OF INTENTION TO RE-DRILL OR REPAIL		
OTICE OF INTENTION TO SHOOT OR ACIDIZE.		- 1
OTICE OF INTENTION TO PULL OR ALTER CAS		- 1
OTICE OF INTENTION TO ABANDON WELL		
(INDICATE ABOVE	BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)	<u></u>
·	Hovember 21,	19.
Hernts-Federal	50 ft. from. $\begin{Bmatrix} N \\ SC \end{Bmatrix}$ line and 990 ft. from $\begin{Bmatrix} E \\ W \end{Bmatrix}$ line of sec.	
(1/2 Sec. and Sec. No.)		
lesignated is, Cliff	Rio Arriba Her Herise (County or Subdivision) (State or Territory)	
(Field)	Bet.	
e elevation of the derrick floor a	DOAG 2cg ICACI 19 "Therefor I a	
	DETAILS OF WORK	
	DETAILS OF WORK	
f and amounted deaths to objective	and a show sizes weights and lengths of proposed casings; indicate mudding jobs	, cen
****	sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs points, and all other important proposed work)	
(fter setting \$121' of 52')	casing on bottom at 3121 with 175 sacks of colors of the c	
After setting \$121' of 52' Did not Circulate. Tester after drilling Plug. Test	casing on bottom at 3121 with 175 sacks of colors.  Casing on bottom at 3121 with 175 sacks of colors.  Casing on bottom at 3121 with 175 sacks of colors.  Casing with 1000 lbe for 30 minutes before one of the colors.  On Color Colors.  Color Colors.	
After setting \$121' of 52' Did not Circulate. Tester after drilling Plug. Test	casing on bottom at 3121 with 175 sacks of colors, and one bottom at 3121 with 175 sacks of colors of Casing with 1000 lbe for 30 minutes before the Dia. No Break.	157
Ifter setting 3121' of 52' id not Circulate. Tested after drilling Plug. Test ompany	casing on bottom at 3121 with 175 sacks of colors, and one bottom at 3121 with 175 sacks of colors of Casing with 1000 lbe for 30 minutes before the Dia. No Break.	157
Ifter setting 3121 of 52 of 52 of set	casing on bottom at 3121 with 175 sacks of control of the control	157 M