



# OIL CONSERVATION COMMISSION

STATE OF NEW MEXICO  
1000 RIO BRAZOS RD. - AZTEC

87410

LAND COMMISSIONER  
PHIL R. LUCERO

DIRECTOR  
JOE D. RAMEY



STATE GEOLOGIST  
EMERY C. ARNOLD

August 9, 1976

Mr. George T. Slaughter  
Petroleum Consultants, Inc.  
Suite 202  
1420 Carlisle, N. E.  
Albuquerque, New Mexico 87110

Re: Petroleum Consultants, Inc.  
Connie #5, G-21-24N-7W

Dear Mr. Slaughter:


Please file a detailed program for your proposed casing repair for the subject well.

Rule 108 requires the operator of a well with defective casing to proceed with diligence to repair or to plug the well.

If remedial action has not commenced as of October 31, 1976, a hearing will be called to allow all interested parties to appear to justify the well remaining in violation of the Rules and Regulations.

If there are questions, please contact us.

Yours very truly,

  
A. R. Kendrick  
Supervisor, District #3

ARK:mc

Attachment

xc: Oil Conservation Commission  
Santa Fe, New Mexico

U. S. G. S.  
Durango, Colorado