OIL CONSERVATION COMMISSION

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO

March 14, 1961

Val R. Reese & Associates, Inc. Lobby, Simme Building Albuquerque, New Mexico

Gentlemen:

The packer leakage test submitted on your Lybrook #1-19 well in Unit G, Section 19-24N-FW on March 7, 1961 indicates that there is a possibility of communication between the Gallup and Dakota producing zones. It is possible that the pressure decrease on the shut in zone on both tests is due to liquid build-up. I am, therefore, directing that this well be re-tested and that the shut-in bottom hole pressures be recorded with a pressure bomb in order to determine if there is leakage.

If you have any questions regarding the above, please contact us.

Yours very truly

Emery C. Arnold Supervisor, District #3

BCA 1 ks

cc: Oil Conservation Commission Santa Fe. N.M.

DIL CONSERVATION COMMISSION

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO

12.12 July 1.35 S.

ing in the second of the secon

Centlames!

షిక్ అ**నిట** త్రిమంలో ఉంది. ద్వారంలో ఆమెక్ట్రామ్ కార్యాన్ని కాట్టిందిని కాట్టికి కాట్టికి ఆమెక్ట్ కాట్టికి కాట్టికికి కాట్టికి కాట్

Youre very 150 L.

นักษณะ จันภูติพยศักราช เก็บราชาวาร คำภู

oot - 911 Conservation Conduction Canta Rey 601.