

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PRODUCTION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company TIDAL OIL COMPANY				Address 435 Petroleum Club Building, Denver 2, Colo.			
Lease McKay-Tidal	Well No. 1	Unit Letter N	Section 14	Township 24 North	Range 2 West		
Date Work Performed	Pool Wildcat			County Rio Arriba			

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☐ Other (Explain):
☒ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Well was permanently P & A in the following manner. Tubing is plugged w/steel swab and 2600' of 9/16" swab line. Hole was then filled w/ drilling mud and 2-7/8". Backed off @ 2200', i. e. top of cement.

Well has been released to land owner who will recomplete as a water well @ approximately 200' after setting a cement plug below his proposed producing horizon.



Witnessed by <i>[Signature]</i>	Position President	Company AGRIEN DRILLING COMPANY
------------------------------------	------------------------------	---

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P BTD	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by <i>[Signature]</i>	Name
Title Supervisor Dist. # 3	Position
	Company

Well site
Memo

From

A. R. KENDRICK

To Charles:

Horace Mr. Kay
told me that he has
no objection to
Mr. Price using this
for a water well
IF Mr. Price will put
a good cement plug
below the water sand.

INSPECTION TICKET

8-4-75

INSTALLATION ABANDONED well LOCATION ^{S/W} ^{S/E} 4915-24-2
OPERATOR TIDAL OIL CO. NEEDS SIGN _____
POOL W.C. FORMATION _____

LOCATION:CLEAN _____ JUNKY ☒ WEEDS _____

OIL & WATER SPILL _____

EDGES SUNKYGENERAL APPEARANCE POORPITS:DIKE GOOD COVERED NEEDS WORK _____

FENCE GOOD _____ NEEDS WORK _____

CONTAINS OIL _____ AMOUNT _____

CONTAINS WATER _____ AMOUNT _____

PRODUCTION EQUIPMENT: NONE TANKS:

PUMP _____ BELT GUARD _____ FENCE _____

NUMBER 0 SIZES _____

SEPARATOR _____ DEHY _____ COMP _____

CLEAN _____ DIRTY _____

CLEAN _____ DIRTY _____ WEEDS _____

OVERFLOW TO PIT _____

SAFE _____ FIRE HAZARD _____

LOAD LINE OK _____ PUDDLES OF OIL _____

PIPED TO PIT _____ TANK _____

LEAKS _____ FIRE HAZARD _____

LEAKS _____

FIRE WALLS _____ GOOD _____ NEED WORK _____

FLOWS TO PIT _____ GROUND _____

FIRE WALL REQUIRED _____ RECOMMENDED _____

CATHODIC PROTECTION UNIT _____

INSPECTED BY: Ch. Johnson

OWNER NOTIFIED BY MAIL, PHONE, DATE _____ OFFICE _____

OTHER REMARKS:UNCASED - 8 5/8" SURFACE PIPE