Budget Bureau No. 42-R358.4. Approval expires 12-31-60.

Form 9-881a. (Feb. 1951)

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. NM 03595
Unit Elizabeth Federal

REGEIVED

SUNDRY NOTICES AND REPORTS ON WELLS.

SUBSEQUENT REPORT OF WATER SHUT-OFF.
SUBSEQUENT REPORT OF SHOOTING OR ACIDERING OF SHOOTING
SUBSEQUENT REPORT OF ALTERING CASING
SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.
SUBSEQUENT REPORT OF ABANDONMENT
SUPPLEMENTARY WELL HISTORY.
-

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

		***************************************	December 11	, 19 61
Well No5 is located	1850 ft. fr	om. $\begin{cases} \mathbf{N} \mathbf{C} \mathbf{K} \\ \mathbf{S} \end{cases}$ line	and 790 ft. from E	line of sec. 18
NE/4 SE/4 Sec. 18	24N	7W	N.M.P.M.	I
(% Sec. and Sec. No.) Escrito (Gallup)	(Twp.) Rio	(Range) Arriba	(Meridian)	Mexico
(Field)	(Coun	ty or Subdivision)		Territory)

The elevation of the derrick floor above sea level is 7180 ft. Estimated

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded well 7:00 A.M. 12/7/61.

Set 215 ft 8-5/8" OD 24# Rg 2 Smls surface casing @ 7:30 P.M. 12/7/61, circulated 150 sacks cement to surface.

Drilling @ 3130 ft 12/11/61.



I understand that this plan of work must receive approval in writing by	the Geological Survey before operations thay be commenced.
Company Dorfman Production Company	
Address 836 Mercantile Dallas Buildi	
Dallas 1, Texas	By S. L. Florsheim Jr.
	S. L. Florsheim Jr. Title General Manager

*** *** *** *** ***