

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

|                                                                                                                                                                      |  |                                                                                  |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|----------------------------------------------------------------------------------|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>                                                     |  | 5. LEASE DESIGNATION AND SERIAL NO.<br><b>SY-078628</b>                          |
| 2. NAME OF OPERATOR<br><b>J. Gregory Harrison</b>                                                                                                                    |  | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME                                             |
| 3. ADDRESS OF OPERATOR<br><b>P.O. Box 507 Farmington, New Mexico 87401</b>                                                                                           |  | 7. UNIT AGREEMENT NAME<br><b>Canyon Largo Unit</b>                               |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)<br>At surface<br><b>990' SWL and 1850' SWL</b> |  | 8. FARM OR LEASE NAME<br><b>Canyon Largo</b>                                     |
| 14. PERMIT NO.                                                                                                                                                       |  | 9. WELL NO.<br><b>132</b>                                                        |
| 15. ELEVATIONS (Show whether DF, RT, GR, etc.)<br><b>6670 SL 6680 KB</b>                                                                                             |  | 10. FIELD AND POOL, OR WILDCAT                                                   |
|                                                                                                                                                                      |  | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA<br><b>Section 15, T24N, R6W</b> |
|                                                                                                                                                                      |  | 12. COUNTY OR PARISH<br><b>Hio Arriba</b>                                        |
|                                                                                                                                                                      |  | 13. STATE<br><b>New Mexico</b>                                                   |

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
(Other) ☐

PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
ABANDON\* ☒  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐  
FRACTURE TREATMENT ☐  
SHOOTING OR ACIDIZING ☐  
(Other) ☐

REPAIRING WELL ☐  
ALTERING CASING ☐  
ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Well has developed casing leak.

Prepare to plug well as follows:

Run 1 1/4" tubing to 3750'. Spot 25 sack cement 3750-4000. Pull 1 1/4" tubing. After cement sets, pump rubber plug down 2 7/8" casing and follow with wire line to locate Mesaverde corrosion hole (probably in 3800-4300 area). Establish injection rate, mix 50 sack cement and displace to 3700'. (Leaving approximately 15 sack in 2 7/8 and squeezing 35 sack outside.) Shoot off 2 7/8" at 2100. Spot 30 sack plug 2100-2000. Spot 20 sack in and out of bottom of surface casing 135-70. 10 sack in top of surface casing. Erect marker and clean location.

18. I hereby certify that the foregoing is true and correct

SIGNED

*J. Gregory Harrison*

TITLE

Operator

DATE

May 8, 1975

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

## Instructions

**General:** This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

**Item 4:** If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

**Item 17:** Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.