(SUBMIT IN TRIPLICATE)

CRIPLICATE) Lease No. 078077 STATES Unit 3.001 Government

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL			
MOTICE OF IMITATION TO DVIPE		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZE	NG
NOTICE OF INTENTION TO TEST WATER SH		SUBSEQUENT REPORT OF ALTERING CASING	1 1
NOTICE OF INTENTION TO RE-DRILL OR RI		SUBSEQUENT REPORT OF RE-DRILLING OR REPA	IR
NOTICE OF INTENTION TO SHOOT OR ACID		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			
(INDICATE AB	OVE BY CHECK MARK NAT	TURE OF REPORT, NOTICE, OR OTHER DATA)	
	 -	August 24	, 19 <u></u>
/ell No. 1-2 is located	1115 ft. from	$\left\{\begin{array}{l} N \\ N \end{array}\right\}$ line and $\left\{\begin{array}{l} 1560 \\ W \end{array}\right\}$ ft. from $\left\{\begin{array}{l} N \\ W \end{array}\right\}$ line	e of sec.
W. Sec. 31	24 회	N.M.P.M.	
(½ Sec. and Sec. No.)	(- WP1)	nge) (Meridian)	
llerd Pictured Cliffs	Rio Arriba (County or St		itory)
(Field)	(County of Se	10017131011	
tate names of and expected depths to obj	ing points, and all othe	weights, and lengths of proposed casings; indicate ir important proposed work)	
.29-00 Total Depth 2216 nis well was Plugged and . Perf at 2107 & squeeze	Abandoned in d w/25 sks. ce	the following manner: D F	GEIVE [
129-0 Total Depth 2216 11s well was Plugged and Perf at 2167 & squeeze 1027 1027 1027 1027 1027 1028	Abandoned in d w/25 sks. ce a pulled. g at 1027'.	the following manner:	GEIVE[JG 26 1900
nis well was Plugged and Perf at 2107 & squeeze Out 7" casing at 1027 Set 25 shs. cement plu Set 15 shs. cement plu Set 5 shs. cement plug	Abandoned in d v/25 sks. ce & pulled. g at 1027'. g at 200'.	the following manner: RECEIVED . S. GE	GEIVE[JG 26 1900 OLOGICAL SURVEY
is well was Plugged and Perf at 2167 & squeeze Cut 7" casing at 1027. Set 25 sks. cement plugget 15 sks. cement plugget 15 sks. cement plugget 15 sks. cement plugget	Abandoned in d v/25 sks. ce & pulled. g at 1027'. g at 200'.	the following manner: RECEIVED . S. GE	GEIVE[JG 26 1980]
is well was Plugged and Perf at 2167 & squeeze Cut 7" casing at 1027 Set 25 shs. cement plus Set 15 sks. cement plus Set 5 sks. cement plus	Abandoned in d v/25 sks. ce & pulled. g at 1027'. g at 200'.	the following manner: RECEIVED . S. GE	GEIVE[JG 26 1900 OLOGICAL SURVEY
is well was Plugged and Perf at 2167 & squeeze Cut 7" casing at 1027 Set 25 shs. cement pluget 5 shs. cement pluget 5 shs. cement pluget 5 shs. cement pluget 5 shs. cement plug	Abandoned in d v/25 sks. ce & pulled. g at 1027'. g at 200'.	the following manner: RECEIVED . S. GE	GEIVE[JG 26 1900 DLOGICAL SURVEY
is well was Plugged and Perf at 2157 & squeeze Cut 7" casing at 1027. Set 25 shs. cement plugget 15 sks. cement plugget 5 sks. cement plugget 6 sks. cement 6 sks.	Abandoned in d w/25 sks. ce & pulled. g at 1027'. g at 200'. s at surface.	the following manner: DE MERCEVED A. S. GER ARMING OIL CON. COM.	GEIVE JG 26 1960 DLOGICAL SURVEY STON, NEW MEXICO
is well was Plugged and Perf at 2167 & squeeze Cut 7" casing at 1027 Set 25 shs. coment plugget 15 sks. coment plugget 5 sks. coment plugget 5 sks. coment plugget 4" x 4" pipe as pe	Abandoned in d w/25 sks. ce & pulled. g at 1027'. g at 200'. s at surface.	the following manner: DE MERCEVED A. S. GER ARMING OIL CON. COM.	GEIVE JG 26 1960 DLOGICAL SURVEY STON, NEW MEXICO
is well was Plugged and Perf at 2107 & squeeze. Cut 7" easing at 1027. Set 25 shs. coment pluses to 15 sks. coment pluses to 4" x 4" pipe as perfect that this plan of work many than the plan the plan the plan t	Abandoned in d v/25 sks. ce & pulled. g at 1027'. g at 200'. st surface. rmement marker	the following manner: DE MERCEVED A. S. GER ARMING OIL CON. COM.	GEIVE JG 26 1960 DLOGICAL SURVEY STON, NEW MEXICO
his well was Plugged and Perf at 2107 & squeeze Cut 7" easing at 1027 Set 25 sks. cement plu Set 15 sks. cement plu Set 5 sks. cement plu Set 4 x 4 pipe as pe	Abandoned in d v/25 sks. ce & pulled. g at 1027'. g at 200'. st surface. rmement marker	the following manner: DE MERCEVED A. S. GER ARMING OIL CON. COM.	GEIVE JG 26 1960 DLOGICAL SURVEY STON, NEW MEXICO
nis well was Plugged and Perf at 2107 & squeeze Cut 7" ensing at 1027 Set 25 sks. cement plu Set 15 sks. cement plu Set 5 sks. cement plue Set 4" x 4" pipe as pe	Abandoned in d w/25 sks. ce & pulled. g at 1027'. g at 200'. at surface. armament marker was receive approval in was treceive approval in was Gas Company	the following manner: DE EMERIT. ALCEVED J. S. GEL ARMING AUG 29 1960 OIL CON. COM. Piting by the Geological Survey before operations	GEIVE JG 26 1960 DLOGICAL SURVEY STON, NEW MEXICO may be commenced.
nis well was Plugged and Perf at 2157 & squeeze. Cut 7" casing at 1027. Set 25 sks. cement plus Set 15 sks. cement plus Set 5 sks. cement plus Set 4" x 4" pipe as performed that this plan of work multiple and performed that the performed tha	Abandoned in d w/25 sks. ce & pulled. g at 1027'. g at 200'. at surface. armament marker was receive approval in was treceive approval in was Gas Company	the following manner: DE MERCEVED A. S. GER ARMING OIL CON. COM.	GEIVE JG 26 1960 DLOGICAL SURVEY STON, NEW MEXICO
is well was Plugged and Parf at 2167 & squeeze. Cut 7" easing at 1027. Set 25 sks. coment plus. Set 15 sks. coment plus. Set 5 sks. coment plus. Set 4" x 4" pipe as per lunderstand that this plan of work multiple as per lunderstand that this plan of work multip	Abandoned in d w/25 sks. ce & pulled. g at 1027'. g at 200'. at surface. armament marker was receive approval in was treceive approval in was Gas Company	the following manner: DE EMERIT. ALCEVED J. S. GEL ARMING AUG 29 1960 OIL CON. COM. Piting by the Geological Survey before operations	GEIVE JG 26 1960 OLOGICAL SURVEY STON, NEW MEXICO may be commenced.

