#### District Office

State of New Mexico Energy, Minerals and Natural Resources

Form C-103 Revised March 25,1999

FEE

DISTRICT I

1625 N. French Dr., Hobbs, NM 87240

OIL CONSERVATION DIVISION DISTRICT II

811 South Frist, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

DISTRICT IV 2040 South Pacheco, Santa Fe NM 87505 2040 S. Pacheco

Santa Fe, NM 87505

WELL API NO

30	03	90	56	342

5. Indicate Type of Lease STATE 🗸

State Oil / Gas Lease No

E-1207

ADD NOT TISE THIS ECOM FOR DRODOSALS TO DOME OF TO DEEDEN OR DEGREE BARKETO. I	7. Lease Name or Unit Agreement Name
(FORM C-101) FOR SLICH PROPOSALS (1)	FARMING E

(FORM C-101) FOR SUCH PROPOSALS

OIL 1. Type of Well: WELL WELL OTHER

2. Name of Operator FOUR STAR OIL AND GAS COMPANY

3300 N. Butler Ave. Ste 100

Farmington

NM 87401

Range R06W

8. Well No

9. Pool Name or Wildcat DEVILS FORK GALLUP/ASSOCIATED)

3

4. Well Location

3. Address of Operator

Feet From The SOUTH Line and 1750

Feet From The WEST

RIO ARRIBA COUNTY

Township\_T24N

10. Elevation (Show whether DF, RKB, RT,GR, etc.)

6482

NMPM

Line

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF IN	TENTIC	ON TO:		SUBSEQUE	NT REPORT OF:	
PERFORM REMEDIAL WORK		PLUG AND ABANDON		REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON		CHANGE PLANS		COMMENCE DRILLING OPERATION	PLUG AND ABANDONMENT	
PULL OR ALTER CASING				CASING TEST AND CEMENT JOB	DHC-24°C	1
OTHER:			=	OTHER: down ho	le commingle	<b>Y</b>
	**					

Four Star Oil and Gas Co. has completed the following in the subject well.

4/27/00 Move in and rig up, nipple down wellhead and nipple up BOP. Trip out of hole with 129 joints 2-1/16" hydrill tubing(4160'), last joint came came apart. Rig up pump and pump down long string.

4/28/00 Rig up wire line specialities and run inhole with freepoint indicator on long string to 6608'. Found tubing free at 5560'. Trip out of hole with tools and run in hole with chemical cutter and cut at 5560'. Trip out of hole with tools.

5/01/00 Trip in hole with 4-11/16" overshot and 2" grapple, 2-3/8" EUE J-55 tubing to top of fish at 4160', Latched onto fish and trip out of hole with 45 joints of 2-1/16" tubing.

5/02/00 run in hole with 4-11/16" overshot and 2" grapple to top of fish at 5560', latch onto fish and retrieve 28 joints 2-1/16" tubing and Baker seal assembly

5/03/00 Run in hole with packer retrieving assembly with grapple, 4 joints drill collars and fishing jars to top of Baker Model D drillable packer. Pick up power swivel and mill 2' and retrieved packer. Trip out of hole.

5/04/00 Run in hole with casing scrapper and tag fill at 6638'. Trip out of hole. Run in hole with 5-1/2" RBP, 5-1/2" packer and 2-3/8" tubing to 5485'. Set RBP, pull up hole with packer and set at 5300', test RBP to 2000psi, release packer and proceed to look for hole in casing. Found bottom of hole at 4124' and top of hole at 3614', trip out of hole.

5/05/00 Trip in hole to retrieve RBP, trip out with RBP, trip in hole to fill at 6620', clean out to PBTD at 6696'

5/08/00 Tag fill at 6643' and clean out to 6696'.

5/09/00 Tag fill at 6696', trip out. Run in hole with production string as follows: 2-3/8" knotch collar, 2-3/8" seating nipple, 58 joints 2-3/8" EUE J-55 tubing(1833'), 5-1/2" X 2-3/8" uni VI packer, XL on/off tool, 147 joints 2-3/8" EUE J-55 tubing(4779'), set packer at 4794'. End of tubing at 6532'. Nipple down BOP and nipple up wellhead and swab.

DATE05/1	6/2000
Telephone No. 3	25-4397

<sup>12.</sup> Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.



# FARMING E No. 3

# current completion

#### LOCATION:

1850' FSL &1750' FWL Sec. 2, T24N, R6W Rio Arriba County, NM

SPUD DATE: 6/21/60

COMPL. DATE: 8/31/60

ELEVATION: 6492' KB

6482' GL

5500 psi

### **FORMATION TOPS:**

Pictured Cliffs 2222' Lewis Shale 2297' Chacra 3030' Mesaverde 3734' Gallup 5479' Greenhorn 6416 Dakota 6505' Morrison 6007'

