

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42 R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF 078922

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR
El Paso Natural Gas Company

3. ADDRESS OF OPERATOR
P. O. Box 990, Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1650' N, 1650' E

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)
6948' GL

7. UNIT AGREEMENT NAME
Canyon Largo Unit

8. FARM OR LEASE NAME
Canyon Largo Unit

9. WELL NO.
96 (P&A)

10. FIELD AND POOL, OR WILDCAT
Ballard P.C.

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
Sec. 3, T-24-N, R-7-W
NMPM

12. COUNTY OR PARISH 13. STATE
Rio Arriba New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well was plugged and abandoned 4-22-77 as follows:

Pressure tested casing, would not hold.

Spotted 20 sacks cement over Pictured Cliffs perfs. Squeezed 10 sacks through perforation. Perfed 4 holes at 1987' and spotted 20 sacks cement.

Squeezed 15 sacks through perfs at 250 PSI. Shot off 2 7/8" casing at 590' and spotted 60 sacks cement plug on stub.

Spotted 60 sacks cement plug at 150' to cover surface casing.

Installed P & A marker at surface with 10 sacks cement plug.

18. I hereby certify that the foregoing is true and correct

SIGNED *J. D. Busco*

TITLE Drilling Clerk

DATE May 13, 1977

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side