

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT --" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well: ☒ OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
FOUR STAR OIL AND GAS COMPANY

3. Address and Telephone No. 3300 N. Butler Ave., Suit Farmington NM 87401 325-4397

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter B : 660 Feet From The NORTH Line and 1980 Feet From The

EAST Line Section 05 Township T24N Range R05W

5. Lease Designation and Serial No.

JIC 68

6. If Indian, Alottee or Tribe Name

JICARILLA

7. If Unit or CA, Agreement Designation

8. Well Name and Number

JICARILLA B

11

9. API Well No.

3003905682

10. Field and Pool, Exploratory Area
OTERO GALLUP

11. County or Parish, State

RIO ARRIBA , NM

12. Check Appropriate Box(s) To Indicate Nature of Notice, Report, or Other Data

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Attering Casing
☐ OTHER: _____
- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work,)*.

FOUR STAR OIL AND GAS CO. PLANS TO PLUG AND ABANDON THE SUBJECT WELL. PLEASE SEE ATTACHED PROCEDURE AND WELLBORE DIAGRAMS.

RECEIVED
APR - 4 1997
OIL & GAS DIV
BUREAU OF LAND MANAGEMENT

14. I hereby certify that the foregoing is true and correct

SIGNATURE *Ted A. Tipton*

TITLE Operating Unit Manager

DATE 1/27/97

TYPE OR PRINT NAME Ted A. Tipton

(This space for Federal or State office use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

COA's For *Bureau restoration in attached letter.*
FILE

DATE APR 2 1997

JICARILLA B #11

PLUG AND ABANDONMENT PROCEDURE

1. Notify Mr. Erwin Elote with the Jicarilla Apache Tribe at 505-759-3242 and Mr. Al Yepa with the Cuba BLM field office at 505-289-3748 at least 24 hours (48 if possible) before plugging operations commence. Office hours: 7:45 a.m. to 4:30 p.m.
2. MIRU well service unit. Install BOP. POOH with 2-3/8" tbg.
3. RIH with 5-1/2" CIBP on tbg or wireline. Set CIBP at 5789'. Fill wellbore with lease water.
4. RU Dowell. Spot 100 feet, (5689'-5789', 12 sacks) cement plug on top of CIBP. POOH.
5. RU wireline. Perforate 2 squeeze holes at 4122'. RIH with 5-1/2" cement retainer on tbg. Set retainer at 4072'.
6. Squeeze 56 sacks class G cement into Mesaverde/Cliff House perms. Sting out of retainer and spot 50 ft (6 sacks) sacks on top of retainer. Pull up 2 joints and reverse out excess cement. POOH.
7. Spot a balance cement plug inside casing acrossed the Chacra, Pictured Cliffs, Fruitland, Kirtland and Ajo Alamo formations: from 3410'-1683' (201 sacks class G neat cement).
8. RU wireline. Perforate 2 squeeze holes at 372'.
9. Open bradenhead valve. Pump into squeeze holes with water and establish circulation to surface. Pump 220 sacks class G cement circulating cement to surface leaving cement inside casing and outside casing at surface. 170 sacks to circulate outside casing and 50 sacks to fill casing from 372'.
10. Cut off wellhead. Erect P&A marker. Remove rig anchors or cut off at least 2' below ground level. Clear and clean location. Reseed location and access road with native grasses as per BLM requirements.
11. Notify EA to file Subsequent sundry.

1/27/97



JICARILLA B No. 11

Current Conditions

LOCATION:

660' FNL & 1980' FEL
NE/NW, Sec. 5, T25N, R5W
Rio Arriba County, NM

ELEVATION: 6645' DF
6635' GR

SPUD DATE: 6/13/58

COMPL DATE: 7/31/58


FORMATION TOPS:

Nacimiento 119'
Ojo Alamo 1783'
Kirtland 2188'
Fruitland 2367'
Pictured Cliffs 2518'
Lewis 2605'
Chacra 3360'
Cliff House 4072'
Menefee 4158'
Pt. Lookout 4720'
Mancos 4863'
Gallup 5839'

GALLUP PERFS:

5876'-5890'
5894'-5998'
5912'-5924'
5936'-5956'
5969'-5976'
4 Bullets/Ft.

*Frac w/ 36,540 Gals. Lse Oil
& 22,000# 20-40 Sand
IPFH: 83 BOPD*



1/27/97



JICARILLA B No. 11

Plugged & Abandoned Conditions

LOCATION:

660' FNL & 1980' FEL
NE/NW, Sec. 5, T25N, R5W
Rio Arriba County, NM

ELEVATION: 6645' DF
6635' GR

SPUD DATE: 6/13/58
COMPL DATE: 7/31/58

FORMATION TOPS:

Nacimiento 119'
Ojo Alamo 1783'
Kirtland 2188'
Fruitland 2367'
Pictured Cliffs 2518'
Lewis 2605'
Chacra 3360'
Cliff House 4072'
Menefee 4158'
Pt. Lookout 4720'
Marcos 4863'
Gallup 5839'

GALLUP PERFS:

5876'-5890'
5894'-5998'
5912'-5924'
5936'-5956'
5969'-5976'
4 Bullets/Ft.

*Frac w/ 36,540 Gals. Lse Oil
& 22,000# 20-40 Sand
IPFH: 83 BOPD*

