

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

JICARILLA CONTRACT #34

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

JICARILLA APACHE TRIBE  
UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

9. WELL NO.

JICARILLA "C" #22

10. FIELD AND POOL, OR WILDCAT

OTERO GALLUP

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

SEC 33 T25N - R5W

12. COUNTY OR PARISH 13. STATE

RIO ARRIBA NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED  
FEB 13 1995  
OIL CON. DIV.  
DIST. 3

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

DOYLE E. BAXTER

3. ADDRESS OF OPERATOR

P.O. BOX 27, BLOOMFIELD NEW MEXICO 87413

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)

At surface

1980' FNL & 660' FEL

"H" SEC 33 T25N - R5W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6793 Gr.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) REENTRY WORK OVER ☒

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.) \*

THIS IS A FAMILY OWNED WELL. ONE MEMBER OF THE FAMILY MADE OUT A SUNDRY ON 09-16-94 BUT  
FAILED TO MAIL IT. I AM NOW TRYING TO CORRECT ALL OF THIS. MY WIFE AND I HAVE BEEN GONE  
FOR ABOUT 4 MONTHS. I HOPE YOU WILL GIVE ME A 6 MONTH EXTENSION TO P & A. WE PLAN TO PULL  
THE RODS AND TUBING, RUN TUBING BACK WITH PACKER TO ISOLATE ONE ZONE TO SEE IF WE CAN SHUT  
WATER OFF. THE FOLLOWING IS WHAT WE HAVE DONE SO FAR THAT WAS SUPPOSED TO BE MAILED TO YOU  
ON 09-15-94. \*05-09-94 ROAD RIG TO LOCATION, RIG UP, SDFN. \*05-10-94 CREW ON LOCATION, UNS  
PUMP AND PULL OUT OF HOLE W/ RODS AND PUMP. (24 PULL 7/8" AND 55 3/4") RIG UP TO SWAB. 7 RU  
\*0511-94 CREW ON LOCATION, TUBING PRESS 285psi RUN SWAB 3 X, GAS CUT FLUID. PUMP 5bbls 1.5%  
DOWN HOLE AND DISPLACE W/ PRODUCED WATER. SWAB ACID BACK TO PIT SWAB WELL TO TEST TANK, W  
KICKING AND TRYING TO FLOW, SHUT DOWN FOR NIGHT LEFT WELL FLOWING TO TANK 27 bbls LOST.  
\*05-12-94 FLOWING WELL TO TEST TANK WELL DIED MADE 6" IN TANK. \*05-13-94 CREW ON LOCATION,  
RUN SWAB TO 3800' GAS CUT FLUID, WELL DIED. RIG UP TO PULL TUBING, LOAD TUBING W/ 27bbls 2%  
WATER, GO DOWN AND CATCH AD-1 PACKER. TRIP OUT OF HOLE W/ PACKER, PICK UP MUD ANCHOR W/ 4'  
PERFORATED SUB, SEATING NIPPLE AND TRIP IN HOLE. TAG TD AND PICK TUBING UP ONE JOINT, LAND  
TUBING (199 JTS) AND HOOK UP WELL HEAD PICK UP PUMP, TOP HOLE DOWN (2x 1 1/2"x 18") TRY TO PUMP  
TUBING PUMP UP ON SURFACE, DID NOT PUMP UP. TOTAL FLUID TO RECOVER= 134 bbls SDFN\*\*NOTE:  
PUMP DID NOT ACT RIGHT SENT PUMP BACK TO PUMP SHOP. \*05-14-94 CREW ON LOCATION. PICK UP PUM  
AND TRIP IN HOLE W/ PUMP AND RODS. SPACE OUT AND HANG ON SEND CREW HOME. WATCH PUMP ACTION  
ACTION GETTING VERY WEAK AND QUIT. LOWER RODS TO TAG HARDER, STILL NO PUMP ACTION, PUMP ST  
IN DOWN POSITION, TUBING WENT ON VACUUM. SDFN. \*05-15-94 SHUT DOWN W.O. ORDERS. \*05-16-94  
CREW ON LOCATION, UNSEAT PUMP AND PULL OUT OF THE HOLE, LAY PUMP DOWN, PULL ROD STUCK IN DOWN  
POSITION. RIG UP TO SWAB. MADE 12 RUNS, SWABBING PIT. RECOVERED HEAVY MUD, THINNING TO MUD

18. I hereby certify that the foregoing is true and correct

SIGNED Doyle E. Baxter TITLE VICE PRESIDENT

DATE 01-03-95

(This space for Federal or State office use)

Chief, Lands and Mineral Resources

APPROVED BY Robert A. Kent TITLE

DATE 8 Feb 95

CONDITIONS OF APPROVAL, IF ANY:

IF WELL IS NOT RETURNED TO PRODUCTION, P&A  
PROCEDURE MUST BE SUBMITTED BY JUNE 1, 1995.

\*See Instructions on Reverse Side

\*05-16-94 CONT'd) WATER. PULLED AND LAYED DOWN 6 JOINTS. TOTAL IN WELL (193 JTS)  
PICK UP PUMP AND RUN IN HOLE SEAT PUMP AND SPACE OUT, HANG ON. CHECK PUMP ACTION, GOOD NIP  
UP WELL HEAD. LEAVE WELL PUMPING TO TEST TANK. SWABBED 35bbls TO PIT. LOAD 99 BBL'S.  
\*05-17-94 CREW ON LOCATION, WELL MADE 4" IN TANK, PUMPING 100% WATER. REPLACE LARKIN  
PACKING ON WELL HEAD. CASING PRESSURE UP TO 30psi. SWITCH CASING GAS TO MOTOR. RIG DOWN  
PULLING UNIT AND RELEASE. LEAVE WELL PUMPING TO TEST TANK. RECOVERED 7 BBL'S LOAD 92 BBL'S.  
\*05-18-94 WELL PUMPING 100% WATER TO TANK. RECOVERED 26 BBL'S. LOAD TO RECOVER 66 BBL'S.  
\*05-21-94 WELL PUMPING 100% WATER AND 15 BBL'S PER DAY W/ TR. OF GAS.  
\*05-23-94 WELL PUMPING 110% WATER AND 15 BBL'S PER DAY W/ TR. OF GAS.  
\*06-30-94 WELL PUMPING 100% WATER AND 10 BBL'S PER DAY WITH TR. OF GAS.  
\*07-08-94 WELL PUMPING 100% WATER AND 6 BBL'S PER DAY  
\*08-12-94 WELL PUMPING 100% WATER AND 6 BBL'S 1/4ER DAY.  
\*09-15-94 WELL PUMPING 100% WATER AND 3 BBL'S PER DAY W/ TR. OF GAS.

\* WELL SHUT IN.