Form 3169-6

UNITED STATES

EΛ	DR.	AP	DO	N

UNE 1990) DEPARTMENT OF THE INTE		Budget Bureau No. 1004-0135		
BUREAU OF LAND MANAGE	EIVIEIN I	Expires: March 31,1993		
SUNDRY NOTICES AND REPOR	5. Lease Designation and Serial No. Contract # 34			
Do not use this form for proposals to drill or to deeper "APPLICATION FOR PERMIT" for		6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE	100 at 10	Jicarilla 7. If Unit or CA, Agreement Designation		
1. Type of Well		- Total of GA, Agreement Designation		
C Oil Gas	TION WELL	8. Well Name and No.		
2. Name of Operator		Jicarilla "C" #12		
TEXACO EXPLORATION AND PRODUCING INC	2.	9. API Well No.		
3. Address and Telephone No.	3003905818			
ARROW N. BUTLER, EARNANCTION, N. M., ATAO.	4 (505)005 4007	10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec.,T.,R.,M., or Su		Blanco South (Pictured Cliffs)		
		11. County or Parish, State		
1650' FWL, 990' FNL, SECTION 33, T25N, R5	RIO ARRIBA, NEW MEXICO			
12. CHECK APPROPRIATE BOX(s)	TO INDICATE NATURE OF NOTICE, REPO	ORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACT	TION		
X Notice of Intent	X Abandonment	Change of Plans		
	Recompletion	New Construction		
Subsequent Report	Plugging Back	Non-Routine Fracti		
Final Abandonment Notice	Casing Repair	Water Shut-Off		
Final Abandonment Notice	Altering Casing Other	Conversion to Inject Dispose Water		
		(Note: Report results of multiple completion on		
		Completion or Recompletion Report and Log for		
 Describe Proposed or Completed Operations(Clearly state all pertinent of give subsurface locations and measured and true vertical depths for 	details, and give pertinent dates, including estimated date of starting ant or all markers and zones pertinent to this work.)*	proposed work. If well is directionally drilled,		
Texaco proposes to plug and abandon the subjection Tentative start date is December 1,1994	ect well. See the attached procedure and wellbo	ore diagrams for pertinent details.		
		<u></u>		
		Peceived		
		NOV 1 0 1994		
		OIL CON. DIV. Dist. 3		
14. I hereby certify that the forgoing is true and co	rrect			

78027	Title Area Manager		7-19.94	
ederal or State office use)	Color Lands and Mineral Resource			
(URIG. SGD.) DAVID R. DITZETS	Title		NOV	8 1994
		_		
1001, makes it a crime for any person knowingly and willfully	o make to any department of agency of the United States any false, fictitious or fra	udulent statement	:	
	(URIG. SGD.) DAVID R SHOPE Proval, if any:	Chief, Lands and Mineral Resources (URIG. SGD.) DAVID R. SHIPER Title	Chief, Lands and Mineral Resources (URIG. SGD.) DAVID R. SB74.79 Title Date	(URIG. SGD.) DAVID RESULTS. Title Area Manager Chief, Lands and Mineral Resources Title NOV

JICARILLA "C" #12

PLUG AND ABANDONMENT PROCEDURE

- 1. MIRUSU. Remove wellhead. NUBOP. Notify BLM to witness.
- 2. POOH w/ TBG and PKR. GIH w/ 5-1/2" CIBP. Set CIBP @ 3500'. Spot "Litepoz" CMT from 3500'-2100' (~104 sx or 34 Bbls). SDFN
- 3. RU wireline. (cement top must be above 2240'). Perforate CSG w/ 2 SPF @ 1070'.
- 4. RIH w/ 5-1/2" CMT RET. Set RET @ 1018'. Open bradenhead. Attempt to circulate to surface through squeeze holes @ 1018'. If circulation is achieved, circulate CMT to surface (Annular volume ~ 45 bbls). Sting out of RET and spot CMT from 1018 surface'. If circulation is not obtained, cement in/out of casing from 300' to surface.
- 5. Remove all surface equipment. Reclaim location. Erect P & A marker.

NOTE: All depths measured from KB or 5' above 10-3/4" casing flange...


DATE: 9/28/90

TEXACO USA

PBTD - 3690' TD - 3750'

JICARILLA C No. 12

PROPOSED PLUG AND ABANDONMENT



DATE: 9/28/90

TEXACO USA MIDLAND PRODUCING DIVISION FARMINGTON AREA

JICARILLA C No. 12 CURRENT WELLBORE

JICARILLA C No. 12

CIRC CMT 10 3/4", 32.75#, H-40 CSG @ 231' W/ 250 SX CMT

ELEVATION:

6735' D.F.

WELL:

LOCATION: NE/4 NW/4 SEC 33 T25N R5W

FORMATION TOPS:

NACIMIENTO - 1018' OJO ALAMO - 2290' KIRTLAND - 2404' FRUITLAND - 2470' PICTURED CLIFFS - 2708' CHACRA - 3541'

COMPL DATE:3-57

TOC @ 1825' BY TEMP SURVEY CMT W/ 400 SX

PICTURED CLIFFS **PERFORATIONS** 27141-27271

PACKER @ 3469'

5 1/2", 14# J-55 CSG @ 3735 W/ 400 SX

> PBTD - 3690' TD - 3750'

CHACRA **PERFORATIONS** 3550'-3680'