

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS


(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Lynco Oil Corporation	8. Farm or Lease Name Regina
3. Address of Operator 5290 DTC Parkway Building #2	9. Well No. 9
4. Location of Well UNIT LETTER <u>P</u> <u>790</u> FEET FROM THE <u>South</u> LINE AND <u>790</u> FEET FROM THE <u>East</u> LINE, SECTION <u>34</u> TOWNSHIP <u>24N</u> RANGE <u>1W</u> NMPM.	10. Field and Pool, or Wildcat Undesignated Fruitland
15. Elevation (Show whether DF, RT, GR, etc.) 7272	12. County Rio Arriba

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set cement plug from 2880 to 2700 (Perforations 2863-67, 4/foot).  
Perforate @ 1680 with 2 holes. Set cement plug from 1680 to 1600.  
Perforate @ 1175 with 2 holes. Set cement plug from 1175 to 1150. Set 50' surface  
plug with 4½ tied to inside 8 5/8. Set 4' steel marker on top  
Work will commence later part of July depending on rig availability.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>James M. Ray</u>	TITLE <u>Field Superintendent</u>	DATE <u>6-28-78</u>
APPROVED BY <u>Original Sub</u>	TITLE <u>DEPUTY</u>	DATE <u></u>
CONDITIONS OF APPROVAL, IF ANY:		