CORRECTED PLAT (JULY 17, 17,0)

MEXICO OIL CONSERVATION

WELL LOCATION AND ACERAGE DEDICATION PLAT

All distances must be from the outer boundaries of the Section Well No. Lease Operator CHACON FEDERAL RIGHETELD COMPANY ATLANTIC THE County Range Township Unit Letter Section RIO ARRIBA 3 WEST 24 NORTH 30 Actual Footage Location of Well: feet from the EAST line and 800 feet from the SOUTH 800 Dedicated Avereage: Pool Producing Formation Ground Level Elev. 191.97 (S/2)Acres Chacon Dakota Dakota 7233 1. Outline the acerage dedicated to the subject well by colored pencil or hachure marks on the plat below.

- 2. If more than one lease is dedicated to the well, outline each and identify the ownership thereof (both as to working interest and royalty), Atlantic Richfield Company is owner of Section 30.
- 3. If more than one lease of different ownership is dedicated to the well, have the interests of all owners been consolidated by communitization, unitization, force-pooling. etc?

() Yes	() No	If answer is "yes," type of consolidation	
•	, , , , ,	•			

If answer is "no," list the owners and tract descriptions which have actually consolidated. (Use reverse side of this form if necessary.)

No allowable will be assigned to the well until all interests have been consolidated (by communitization, unitization, forcedpooling, or otherwise) or until a non standard unit, eliminating such interests, has been approved by the Commission.

CERTIFICATION

herein is true on knowledge and believe the state of the	the dr.
---	---------

SAN JUAN ENGINEERING COMPANY,

FARMINGTON, N. M.

Certificate No. 1463