Form 9-331 - May 1963

## UNITED STATES SUBMIT IN TRIPLICATE\* DEPARTMENT OF THE INTERIOR (Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

GEOLOGICAL SURVEY	SF-080472-A
SUNDRY NOTICES AND REPORTS ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)	
Use "APPLICATION FOR FERSIT— for sacing proposation	7. UNIT AGREEMENT NAME
OIL FFT GAS	
WE'L GAS WELL OTHER	8. FARM OR LEASE NAME
NAME OF OPERATOR	
Atlantic Richfield Company	Chacon Federal
3. ADDRESS OF OPERATOR	9. WELL NO.
501 Lincoln Tower Bldg., 1860 Lincoln St., Denver, Colo. 802	295 5
4 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.	10. FIELD AND POOL, OR WILDCAT
See also space 17 below.) At surface	Chacon-Dakota
SE SE 850' f/South & 850' f/East lines, Sec. 19	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
2F 2F 620, 1/20001 & 630, 1/ pgs 4 miles 2 26 25	SCRIPT ON RAME
1DT 1/20 020 02/09	Sec. 19-21:N-3W
APT #30-039-21588  14. PERMIT NO.   15. ELEVATIONS (Show whether DF, RF, GR, etc.)	Sec. 19-2LN-3W 12. COUNTY OR PARISH 13. STATE
14. FEM.11 NO.	Rio Arriba New Mexico
Mr. Earrick - 4/18/78   7041' GR; 7055' RKB	ETO RITIDA POR TORIGO
16. Check Appropriate Box To Indicate Nature of Notice, Report	, or Other Data
. 'Yo Indicate .	SUBSEQUENT REPORT OF:
PB Depth	<u> </u>
TEST WATER SHUT-OFF PULL OR ALTER CASING XXTEX SHPTOFF	X REPAIRING WELL
FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	
SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZIN	ABANDONMENT*
REPAIR WELL CHANGE PLANS (Other) Temp.	Abn'cLower Zone (C) Y
(Note: Report Completion or F	results of multiple completion on Well Recompletion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent proposed work. If well is directionally drilled, give subsurface locations and measured and true	t dates, including estimated date of starting any evertical depths for all markers and zones perti-
Top of cement @6330'. Press tested casing prior to gals 15% MCA acid prior to perfig.  10-2-78 Perfid 7493-7505' w/2 jet shot/ft. Ran RTTS pkr on to displace acid. Then set @ 7470' to swab test "0 Pld swab l/lr f/bottom (7470'), last run recid not run brackish clear wtr. No show of oil or gas.  10-4-78 Pmpd in 500 gals 15% MCA, press to 1800-2000# @ 4 w/30 bbls 1% KCl wtr. Strt'd swabbing @ 1:15 pm, 1 bottom 7470', 2 pulls/hr, 200' fluid each pull, bl gas @ 5:30 pm, no recovery. Waited 1 hr & pulled acid wtr, no gas. From 6:30 pm to 6:30 am, 1 swab pulls; avg rec'd 1/2 bbl/hr, brackish acid wtr, no tbg. EP set @ 7480, test. Dumped 1 sx cement on the PED @ 7470'.	perf's, tested Ok. Sptd 250  2-3/8" tbg, set @ approx 7000' " Zone. Ching. Las 6 hrs, 1/L-1/2 bbl/  BPM. ISIP 900#. Displ'd  10/L/78. At 3:30 pm swbd f/  Lack brackish wtr. Slight acid to swab, rec'd 3/L bbl brackish by/hr, none rec'd on some swab o gas or oil. POH w/RTTS pkr &
	*
18. I hereby certify that the horegoing is true and correct	
SIGNED STITLE Operations Info. As	ss't. DATE 11-15-78
(This space for Federal or State office use)	
(This space for redefat or brace office and)	21.00
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	DATE