Form 3160-5 (June 1990)

## UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED Budget Bureau No. 1004-0135

DELTIME	TOT THE INTERIOR	Expires: March 31, 1993
BUREAU OF I	LAND MANAGEMENT	5. Lease Designation and Serial No.
CUMPRY MOTIOFO AND REPORTS ON WELLS		Cont. 148
SUNDRY NOTICES AND REPORTS ON WELLS		6. If Indian, Allottee or Tribe Name
	ill or to deepen or reentry to a different reservoir.	
Use "APPLICATION FOR	R PERMIT—" for such proposals	
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Well	<del></del>	
Oil Sas Other		8. Well Name and No.
2. Name of Operator		Jicarilla Contract 148 #17
Amoco Production Company Attn: John Hampton		9. API Well No.
3. Address and Telephone No.		<del> </del> 30 039 21999
·		10. Field and Pool, or Exploratory Area
P.O. Box 800, Denver, Colorado 80201  4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		Lindrith Gallup-Dakota West
1520' FSL, 870' FEL, Sec. 1	5 T25N-D5ur	11. County or Parish, State
1320 FSE, 070 FEE, Sec. 1	5, 125N-K5W	Rio Arriba, New Mexico
		RIO ALTIDA, New Mexico
12 CHECK ADDRODDIATE BOY	N TO INDICATE NATURE OF NOTICE REPO	DT OP OTHER DATA
12. CHECK APPROPRIATE BOX(	s) TO INDICATE NATURE OF NOTICE, REPO	NI, ON OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
X Notice of Intent	X Abandonment	Change of Plans
Notice of Intent		New Construction
	Recompletion	r1
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	U Other	Dispose Water (Note: Report results of multiple completion on Well
		Completion or Recompletion Report and Log [orm.]
13. Describe Proposed or Completed Operations (Clearly state al	pertinent details, and give pertinent dates, including estimated date of startin	ng any proposed work. If well is directionally drilled,
give subsurface locations and measured and true vertice	al depths for all markers and zones pertinent to this work.)*	
		11
~ ~	ds to Plug and Abandon the subject we	11.
See attached for procedure:		
	<b> </b>	0
	11592 UN 01592	22
	VON UNOM	14 11 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

14. I hereby ceptify that the foregoing is true and correct		APPROVED
Signed John Hamston 10ta	тіне <u>Sr. Staff Admin. Sup</u>	OV. AS AMENDED2
(This space for Federal or State office use)		JUN 0 4 1992
Approved by	Title	<b>Ken To</b> wnsons  ✓ AREA MANAGER


If you have any questions please call Julie Acevedo at 303-830-6003.

# PXA Procedures Jicarilla Contract 148 #17

- Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. NDWH. NUBOPE.
- 3. POOH with 2 7/8 tbg. RIH with tbg and cement retainer. Set retainer at 6300'. Squeeze gallup perfs at 6436' to 6798' with 198 sx of class B cement.
- 4. POOH and spot cement plug to 6200' with 29 sx cement.
- 5. Load hole with 9bls mud/POZ water to 5500'. Spot cement plug from 5500' to 5400' with 29 sx cement and 4700' to 4600'with 29 sx cement. Load hole with 9bls mud/POZ to 4000'.
- 6. RIH with tbg and cement retainer. Set retainer at 3900'. Squeeze chacra with 41 sx cement.
- 7. POOH and spot cement plug to 3700' with 58 sx cement.
- 8. Load hole with 91bs mud/POZ water to 3400'.
- 9. Spot cement plugs as follows to cover producing zones as follows:

3000' to 3400' Fruitland and PC 116sx 2100' to 2400' Ojo Alamo 87sx 1500' to surface 434sx

- 10. NDBOPE. Cut off casing and wellhead. Install PXA maker according to BLM or State requirements.
- 11. Turn over to John Schwartz for reclamation.
- 12. Rehabilitate location according to BLM or State requirements.



#### UNITED STATES DEPARTMENT OF THE INTERIOR

### BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA 1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Well: 17 Jicavilla Confront 148

#### CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."

2. Mark Kelly with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 326-6201.

3. Blowout prevention equipment is required.

4. The following modifications to your plugging program are to be made (when applicable):

1) Spot 50 of cont. on top of Returne 2 7300'

2) Spot 9.0 Hlg. I Mid from 7250' to 6798!

3) Adjust Plug depths as follows

plug from 4000 to \$700'

play from 2970 to 3400

Pluy from 2520 to 2810'

4) Add play from 1932 to 1832! (Top of Naciminto)

Note! It cement was Not circulated to the surface on the squeeze job done on the

Office Hours: 7:45 a.m. to 4:30 p.m.

heles in the casing from 537 to 569; it will be necessary to putante 2 374 and

circulate coment to the surface.