5. LEASE

UNITED STATES DEPARTMENT OF THE INTERIOR

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. ail gas cother	Jicarilla 9. WELL NO.
3. ADDRESS OF OPERATOR Suite 501 1850 Lincoln Street, Denver, Colorado 80295 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 500' FNL & 1650' FWL (NE NW) AT TOP PROD. INTERVAL: (Unit C) AT TOTAL DEPTH: Approx the same 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	114 10. FIELD OR WILDCAT NAME W. Lindrith - Gallup/Dakota 11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA 7-24N-4W 12. COUNTY OR PARISH 13. STATE Rio Arriba New Mexico 14. API NO. 30-039-22160 15. ELEVATIONS (SHOW DF, KDB, AND WD) 6800' GL
SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) N. O. setting production casing	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state a including estimated date of starting any proposed work. If well is dire measured and true vertical depths for all markers and zones pertinent to	ectionally drilled give subsurface locations and
Ran 176 jts. 5-1/2" casing, 33 joints 17# (1376.5 (5939.5), DV tool (4.37') total of 7320.45' and first stage with 10 BW and 1000 gals mud flush at Cement second stage with 300 sxs Phixit. P D @ 4	landed @ 7311'. Cement nd 350 sxs BJ Phixit.
Released rig 9:00 am 11-21-79.	
Waiting on completion.	
Subsurface Safety Valve: Manu. and Type	Set
18. I hereby certify that the foregoing is true and correct Operations	
SIGNED W. A. Walther, Jr. TITLE Manager	DATE11-28-79