

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No. JIC CONTRACT 146
2. Name of Operator AMOCO PRODUCTION COMPANY		6. If Indian, Allottee or Tribe Name JICARILLA
3a. Address P.O. BOX 3092 HOUSTON, TX 77079		7. If Unit or CA/Agreement, Name and/or No.
3b. Phone No. (include area code) Ph: 281.366.4081 Fx: 281.366.0700		8. Well Name and No. JIC CONTRACT 146 32
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 10 T25N R5W NENE 1110FNL 810FEL		9. API Well No. 30-039-22485
		10. Field and Pool, or Exploratory CHACRA / BLANCO MESAVEVERDE
		11. County or Parish, and State RIO ARRIBA COUNTY, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input checked="" type="checkbox"/> Temporarily Abandon <i>MV only</i>	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomple in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Amoco Production Company request permission to T&A the Mesaverde portion of this well and produce only from the upper zone which is the Otero Chacra.

Please see the attached procedure for details.

and 1-14-02

14. I hereby certify that the foregoing is true and correct. Electronic Submission #9829 verified by the BLM Well Information System For AMOCO PRODUCTION COMPANY, sent to the Rio Puerco	
Name (Printed/Typed) CHERRY HLAVA <i>Cherry Hlava</i>	Title SUBMITTING CONTACT
Signature (Electronic Submission)	Date 12/19/2001

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By <i>[Signature]</i>	Lands and Mineral Resources	Date 1/17/02
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**** ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL ****

Jicarilla Contract 146 No. 32
Unit A Sec 10 T25N-R5W
Rio Arriba County, NM
API 30-039-22485

December 13, 2001

Reason for work

Unable to unload the MV. Currently producing the CK up the casing. MV is to be temporarily abandoned with a CIBP.

Procedure:

1. MIRU SU. Record TP and CP. Kill well with clean 2% KCl water. ND tree, NU BOP.
2. Drop down and tag fill. POOH drifting tbg, visually inspecting.
3. Make bit x scraper run to 5403' PBTD.
4. RIH with CIBP on tbg. Set CIBP at +/- 5050'.
5. RIH rabbiting following production string:
 - a) 1 jt 2-3/8" tbg
 - b) F-nipple
 - c) 2-3/8" tbg to surface
6. Land EOT at +/- 4960'.
7. ND BOP, NU tree.
8. Flow well for 2-3 hours, swabbing if necessary.
9. RDMO SU.

Allen Kutch

281-366-7955 office
281-366-0700 fax
888-788-6522 pager

Jicarilla Contract 146 No. 32
12-13-2001
Rio Arriba County, NM
Unit A Section 10 T25N - R5W
Run 65

ATK

KB: 14'

CK Perfs:

4951' - 4956'
4961' - 4966'
4969' - 4979'

MV Perfs:

5112' - 5123'
5127' - 5138'
5162' - 5188'
5253' - 5260'
5282' - 5288'
5316' - 5318'
5324' - 5329'
5339' - 5342'
5380' - 5386'

8-5/8" 24# K55@ 302'
w/ 315 sxs

circ 20 sxs good cmt
to sfc

DV tool @ 4042'
w/130 sxs
Circ cmt both stages

SN @ 5323'

2-3/8" @ 5355'

5-1/2" 15.5# K55@
5418' w/ 770/130
sxs

PBTD: 5403'
TD: 5431'