

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-039-22496

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

2. Name of Operator

NASSAU RESOURCES, INC.

OGRID #015515

3. Address of Operator

P O BOX 809, Farmington, NM 87499

4. Well Location

Unit Letter F : 1520 Feet From The North Line and 1850 Feet From The West Line

Section 33

Township 24N

Range 2W

NMPM Rio Arriba

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

7130 GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was plugged and abandoned on 7/26/94 per attached copy.

RECEIVED
AUG - 1 1994

OIL CON. DIV.
DIST. 3

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Murphy Brasuel
Murphy Brasuel

TITLE Field Supt.

DATE 7/28/94

TYPE OR PRINT NAME

Murphy Brasuel

TELEPHONE NO. 505 326-7793

(This space for State Use)

APPROVED BY

Johnny Robinson

TITLE

Oil & Gas Inspector

DATE

8-25-94

CONDITIONS OF APPROVAL, IF ANY:

July 27, 1994

Page 1 of 1

NASSAU RESOURCES, INC.

Jelly Dog Jerry #1 (PC)

1520' FNL & 1850' FWL

Sec.33, T24N, R2W

Rio Arriba County, NM

FEE Lease

PLUG AND ABANDONMENT REPORT

Cementing Summary:

Plug #1 with 24 sxs Class B cement from 3001' to 2684' over Pictured Cliffs perms.

Plug #2 with 18 sxs Class B cement inside casing from 2801' to 2562' over Fruitland and Ojo Alamo zones.

Plug #3 with 45 sxs Class B from 183' to surface pumped down 4-1/2" casing, circulated 1 bbl good cement out bradenhead.

Plugging Summary:

7-25-94 Safety Meeting. Drive rig to location. Rig up. Pressures: casing 100#, tubing 25#. Lay out relief lines and bleed well down. ND wellhead. NU BOP. PU and RIH with 1 jt 1-1/4" tubing and tag bottom of well at 3005'. POH to 3001'. Plug #1 with 24 sxs Class B cement from 3001' to 2684' over Pictured Cliffs perms. POH to 1940'. Shut in well, WOC. SDFN.

7-26-94 Safety Meeting. Open up well, no pressure. RIH and tag of cement at 2806'. POH to 2801'. Load well with 5 bbls water and pressure test casing to 500#, held OK. Plug #2 with 18 sxs Class B cement inside casing from 2801' to 2562' over Fruitland and Ojo Alamo zones. Perforate 2 squeeze holes at 183'. Dig out wellhead and lay relief line from bradenhead. Establish circulation out bradenhead with 5 bbls water. Plug #3 with 45 sxs Class B from 183' to surface pumped down 4-1/2" casing, circulated 1 bbl good cement out bradenhead. Shut in well, WOC. ND BOP and cut off well head. Install P&A marker with 15 sxs Class B cement. Rig down and move off location.